

Adtran

Adtran Operating System  
R14.4.0 Release Notes

Document Issue: A  
Document Number: 6AOSRN1440-40A

# Disclaimer of Liability

The information or statements given in this document concerning the suitability, capacity, or performance of the mentioned hardware or software products are given “as is”, and any liability arising in connection with such hardware or software products shall be governed by Adtran’s standard terms and conditions of sale unless otherwise set forth in a separately negotiated written agreement with Adtran that specifically applies to such hardware or software products.

To the fullest extent allowed by applicable law, in no event shall Adtran be liable for errors in this document for any damages, including but not limited to special, indirect, incidental or consequential, or any losses, such as but not limited to loss of profit, revenue, business interruption, business opportunity or data, that may arise from the use of this document or the information in it.

“Adtran” and the Adtran logo are registered trademarks of Adtran, Inc. Brand names and product names included in this document are trademarks, registered trademarks, or trade names of their respective holders.

Copyright © 2024 Adtran, Inc.  
All Rights Reserved

# Contents

|  |           |
|--|-----------|
| <b>Disclaimer of Liability</b> .....                         | <b>2</b>  |
| <b>Contents</b> .....  | <b>3</b>  |
| <b>Preface</b> .....   | <b>4</b>  |
| To the Holder of this Document .....                         | 4         |
| Revision History .....                                       | 4         |
| Warranty and Contact Information .....                       | 5         |
| Warranty .....   | 5         |
| Contact Information .....                                    | 5         |
| <b>1. Introduction</b> .....                                 | <b>6</b>  |
| <b>2. Supported Platforms</b> .....                          | <b>7</b>  |
| <b>3. Features and Enhancements in Release R14.4.0</b> ..... | <b>8</b>  |
| <b>4. Fixes</b> .....  | <b>9</b>  |
| General Bug Fixes in R14.4.0 .....                           | 9         |
| Carrier Ethernet Specific Bug Fixes in R14.4.0 .....         | 9         |
| Voice Specific Bug Fixes in R14.4.0 .....                    | 9         |
| <b>5. Errata</b> .....                                       | <b>11</b> |
| General Errata .....   | 11        |
| Carrier Ethernet Specific Errata .....                       | 13        |
| Voice Specific Errata .....                                  | 14        |
| <b>6. System Notes</b> .....                                 | <b>16</b> |
| <b>7. Upgrade Instructions</b> .....                         | <b>17</b> |

# Preface

|                                      |   |
|--------------------------------------|---|
| To the Holder of this Document ..... | 4 |
| Revision History .....               | 4 |

## To the Holder of this Document

This document is intended for the use of Adtran customers only for the purposes of the agreement under which the document is submitted, and no part of it may be used, reproduced, modified or transmitted in any form or means without the prior written permission of Adtran.

The contents of this document are current as of the date of publication and are subject to change without notice.

## Revision History

| Revision | Date      | Description                  |
|----------|-----------|------------------------------|
| Rev A    | June 2024 | Supports AOS version R14.4.0 |

# Warranty and Contact Information

## Warranty

Warranty information can be found at:

[my.adtran.com/warranty](http://my.adtran.com/warranty).

## Contact Information

For all customer support inquiries, please contact ADTRAN Customer Care:

| Contact       | Support                                       | Contact Information   |
|---------------|---|---|
| Customer Care | From within the U.S.<br>From outside the U.S. | 1.888.4ADTRAN<br>(1.888.423.8726)<br>+1.256.963.8716  |
|               | Technical Support:                            | <a href="http://www.adtran.com/support">www.adtran.com/support</a>  |
|               | Training:<br>Email:<br>Web:                   | training@adtran.com<br><a href="http://www.adtran.com/training">www.adtran.com/training</a><br><a href="http://www.adtranuniversity.com">www.adtranuniversity.com</a> |
| Sales         | Pricing and Availability                      | 1.800.827.0807  |

# 1. Introduction

AOS version R14.4.0 is a major system release that introduces new features and addresses bug fixes and customer issues that were uncovered in previous code releases.

This release is generally available code. Results obtained during internal testing have been evaluated and the code has been determined to be ready for general availability. Caveats discovered during testing but not addressed in this build are listed in [5. Errata](#).

Configuration guides, white papers, data sheets, and other documentation can be found on Adtran's Support Forum, <https://supportforums.adtran.com>. The contents of these release notes will focus on the platforms listed in [6. System Notes](#). Additional information specific to AOS is outlined in [6. System Notes](#).

## 2. Supported Platforms

Table 1 lists the platforms that are supported in AOS version R14.4.0. To confirm the Boot ROM version, Telnet or console to the unit and enter the **show version** command. The Boot ROM version will be listed as **Boot ROM version XX.XX.XX**. If you need a Boot ROM upgrade, contact Adtran Technical Support (support@adtran.com or 888-423-8726) for assistance.

**Table 1: Supported Platforms**

| Platform                            | Standard Feature Pack | Enhanced Feature Pack | SBC Feature Pack | Minimum Boot ROM |
|-------------------------------------|-----------------------|-----------------------|------------------|------------------|
| NetVanta 3140                       | ✓                     | ✓                     | ✓                | R11.5.0          |
| NetVanta 3148                       | ✓                     | ✓                     | ✓                | R11.3.0.B3       |
| NetVanta 4148                       | ✓                     | ✓                     | ✓                | R11.3.0.B3       |
| NetVanta 4430                       | ✓                     | ✓                     | ✓                | 17.04.01.00      |
| NetVanta 4660                       |                       | ✓                     | ✓                | R10.10.0.B5      |
| NetVanta 6250                       |                       | ✓                     | ✓                | R10.9.0          |
| Total Access 900 Series (3rd Gen)   |                       | ✓                     |                  | R13.7.0.B1       |
| Total Access 900e Series (3rd Gen.) |                       | ✓                     | ✓                | R10.9.0          |

# 3. Features and Enhancements in Release R14.4.0

This section highlights the major features, commands, and behavioral changes for all products running AOS version R14.4.0.

|           |  |
|-----------|--|
| AD-277426 | Added support for public key authentication to the SSH client.   |
| AD-274043 | Added the ability to configure the enabled key exchange and host key algorithms for the SSH client.  |
| AD-261240 | Added the ability to configure the minimum and maximum SSH moduli lengths.   |
| AD-251342 | Added support for the diffie-hellman-group-exchange-sha256, diffie-hellman-group16-sha512, and ecdh-sha2-nistp256 key exchange algorithms to the SSH server. These algorithms are currently disabled by default. |
| AD-251341 | Added support for the ecdsa-sha2-nistp256, ecdsa-sha2-nistp384, ecdsa-sha2-nistp521, and rsa-sha2-512 host key algorithms to the SSH server. These algorithms are currently disabled by default.                 |



## 4. Fixes

|  |   |
|--|---|
| General Bug Fixes in R14.4.0 .....                   | 9 |
| Carrier Ethernet Specific Bug Fixes in R14.4.0 ..... | 9 |
| Voice Specific Bug Fixes in R14.4.0 .....            | 9 |

### General Bug Fixes in R14.4.0

This section highlights major bug fixes for all products running AOS version R14.4.0.

|           |  |
|-----------|--|
| AOS-44108 | Fixed an issue in which the GUI showed an incorrect number of installed licenses.              |
| AOS-44059 | Fixed an issue in which PPP IPCP negotiation would not complete on the NetVanta 3148 and 4148. |
| AOS-44040 | Fixed an issue in which SCP and SFTP transfers failed when using the unit's DSA private key.   |
| AOS-44032 | Fixed multiple issues causing "test list weighted" to not function properly in tracks.         |
| AOS-44018 | Fixed an issue in which ETH-LM/DM replies did not mirror the proactive flag.                   |
| AOS-44017 | Adjusted the PPPoE restart timer from 1 to 3 seconds on the NetVanta 4660 and 5660.            |

### Carrier Ethernet Specific Bug Fixes in R14.4.0

This section highlights major bug fixes for all products running AOS version R14.4.0.

|           |  |
|-----------|--|
| AOS-44013 | Fixed an issue in which the 24-hour interval SHDSL performance monitoring counters did not roll to the next day at midnight. |
| AOS-43988 | Fixed an issue in which it was possible to set an invalid interface on an Ethernet loopback.                                 |

# Voice Specific Bug Fixes in R14.4.0

This section highlights voice specific bug fixes in AOS version R14.4.0.

|           |  |
|-----------|--|
| AOS-44118 | Fixed an issue in which TLS certificates longer than 4096 bytes were unable to be parsed, which prevented establishment of SIP TLS connections to servers using certificates larger than 4096 bytes.   |
| AOS-44114 | Fixed an issue in which a reboot may have occurred if VQM was used under heavy call load.  |
| AOS-44092 | Fixed an issue in which a reboot may have occurred during a call transfer.   |
| AOS-44064 | Fixed an issue in which a new SIP TLS session was not established after a WAN failover event when operating in client-only mode.   |
| AOS-44037 | Fixed an issue in which an error message stating "VQMManager could not create new stream" may have displayed on the CLI during call setup and VQM may not have collected statistics for all call legs. |

## 5. Errata

|  |    |
|--|----|
| General Errata .....                   | 11 |
| Carrier Ethernet Specific Errata ..... | 13 |
| Voice Specific Errata .....            | 14 |

### General Errata

The errata listed below exist in all products running AOS version R14.4.0.

|           |   |
|-----------|---|
| IN-25468  | The "called-number" command on a Demand Interface does not function properly.   |
| IN-24433  | When using XAUTH with a VPN client, an AOS device requests CHAP authentication from the client, but does not send a CHAP challenge payload. This can cause issues with some VPN clients that expect to receive this payload.  |
| IN-22458  | With FFE enabled, passing traffic from the Ethernet 0/1 interface out an Ethernet NIM2 could cause the Ethernet 0/1 interface to go down. The interface is recoverable with a reboot. Disabling FFE on the Ethernet 0/1 interface prevents the issue.                                     |
| IN-10479  | The name of a deleted IPv4 ACL cannot be used to name a new IPv6 ACL.   |
| AOS-44066 | When using the diffie-hellman-group-exchange-sha256 and diffie-hellman-group16-sha512 key exchange algorithms with moduli larger than 3072 bits, traffic flow may be interrupted for several seconds during SSH negotiation on all platforms other than the NetVanta 3148, 4148 and 5660. |
| AOS-44038 | When a VPN local ID is configured as an ASN.1 DN, the string is improperly capitalized by AOS. Because ASN.1 DN comparison is case sensitive, this will result in ID/cert mismatches when the ASN.1 DN in the cert contains lowercase characters.   |
| AOS-43222 | A SNMP walk may be unable to return some input or output QoS policies assigned to interfaces if multiple interfaces have both input and output QoS policies assigned.   |
| AOS-42891 | On the NetVanta 3148 and 4148, the output of "show power inline" lists 12 gigabit-switchports instead of 8.   |

|           |   |
|-----------|---|
| AOS-42633 | A reboot may occur when running line rate traffic on the NetVanta 3148 and 4148 through an interface that has an access-policy assigned that contains discard entries.  |
| AOS-42583 | On the Total Access 900 Third Generation, a remote payload loopback initiated from the DSX interface (t1 0/2) does not function properly.   |
| AOS-42582 | On the Total Access 900 Third Generation, the Network (t1 0/1) and DSX (t1 0/2) interfaces transmit B8ZS coded signals when configured for AMI coding.  |
| AOS-42208 | The sequence number in the TCP RST generated by the firewall when clearing a policy-session entry does not comply with RFC 793. This issue occurs when clearing a policy-session entry manually via the CLI and during failover if "ip firewall fast-nat-failover" and/or "ip firewall fast-allow-failover" are configured. |
| AOS-41261 | Router advertisements for delegated prefixes assigned to a interface do not use the valid lifetime specified in the received IA_PD Prefix option.<br>Workaround: Configure "ipv6 nd prefix named-prefix <prefix name> <prefix sub-bits>" for each delegated prefix assigned to the interface.                               |
| AOS-39470 | Making any changes in the GUI for an Ethernet interface configured for DHCP causes the DHCP client to perform a DHCP release/renew on that interface when the changes are applied.  |
| AOS-30561 | If a track is configured to monitor the line-protocol of an interface configured for 802.1Q, the track will never go into a passing state even if the interface is up. This issue does not affect the NetVanta 4660, 5660, or 6360. A workaround is to track the line-protocol of the subinterface.                         |
| AOS-28378 | The "clear sip tls session" command does not function.  |
| AOS-25916 | In some command sets, the "exit" command is not visible even though it still functions properly.  |
| AOS-20612 | Speed and duplex settings are displayed on mef-ethernet interfaces in "show running-config verbose", even though those options are not valid or configurable for that type of interface.  |
| AOS-19531 | In the VQM RTP Monitoring menu, the refresh button refreshed the displayed graphic, but it also duplicated information in the lower part of the menu. Also, when the cursor hovered over a data point, it displayed multiple instances of the same data.  |
| AOS-19492 | In the VQM RTP Monitoring menu, the Source IPs and Interfaces menus have invisible data points that appear and display data when the cursor hovers over them. The invisible data point information duplicates a visible data point and can usually be found hidden above the visible data point.                            |

|           |  |
|-----------|--|
| AOS-14421 | The output of "show qos map interface <interface>" shows "ce-vlan-id" instead of "vlan-id" and "ce-vlan-pri" instead of "cos" on products other than the NetVanta 4660, 5660, and 6360.                  |
| AOS-12266 | SFP information for an SFP inserted into a NetVanta 4430 does not display correctly.   |
| AOS-10823 | Ethernet interfaces in 3rd generation TA 900Es can not be seen from the Data > IP Interfaces page in the GUI. These interfaces can be configured from the System > Physical Interfaces page instead.     |
| AOS-8519  | The 3rd Gen. Total Access 900e and NetVanta 6250 send a cold start SNMP trap on reload instead of a warm start trap.   |
| AOS-5580  | If the top level ATM interface on a SHDSL ATM NIM2 module is disabled and re-enabled, the ATM circuit will no longer be able to pass traffic. The ADTRAN unit must be rebooted to correct the problem.   |
| AOS-1653  | Having more than two entries in a Network Monitor ICMP probe test list displays Tracked by: Nothing in the show probe command output. This is only a display error; the probes still function correctly. |
| AOS-1124  | VQM may show a loopback interface in the GUI when a loopback interface is not configured.  |
| AD-255105 | Traffic shaping on VLAN interfaces is not supported on the NetVanta 3148 and 4148.   |

## Carrier Ethernet Specific Errata

The following is a list of Carrier Ethernet specific errata that exist in products running AOS version R14.4.0.

|           |  |
|-----------|--|
| AOS-44169 | The 15-minute interval SHDSL performance monitoring counters reset at midnight.  |
| AOS-43266 | Y.1731 Ethernet Continuity Check (ETH-CC) frames may not be sent at the configured interval if NTP is not configured or synchronized.  |
| AOS-43265 | On the NetVanta 4660, a small percentage of frames may be discarded if NTP is not configured or synchronized.  |
| AOS-41517 | The Invalid CE VLAN ID counter does not function on the GigabitEthernet 0/1 interface on the NetVanta 4660, 5660, and 6360 because GigabitEthernet 0/1 is not intended for use as a UNI interface for Layer 2 services on these platforms. |
| AOS-22021 | The "efm-group" interface type option is missing from the "tunnel source" command on Tunnel interfaces.  |

# Voice Specific Errata

The following is a list of voice specific errata that exist in products running AOS version R14.4.0.

|           |  |
|-----------|--|
| AOS-44135 | RTP may be sourced from the wrong port after processing a 302 Moved Temporarily response in an SBC application.  |
| AOS-41155 | If a voice trunk is removed while calls are active, a reboot may occur.  |
| AOS-37978 | Enabling the SIP stack on a device allocates numerous resources. If this resource allocation fails, the device will reboot. Multiple sockets must be available and local SIP ports, typically UDP and TCP 5060, must be available as well, otherwise the resource allocation will fail and the device will reboot.   |
| AOS-31081 | When using the SIP proxy with media anchoring, VQM reports incorrect information for LocalURI, RemoteURI, and LocalCaller if a reINVITE that modifies the SDP is received from the callee during a call.   |
| AOS-24657 | Issuing the command "clear voice call active" with MGCP calls up may result in a reboot.   |
| AOS-22835 | If "sip tls" is configured and "sip" is disabled, you must first issue "no sip tls" to enable "sip", otherwise the following error will be displayed: "%Error: Failed to modify SIP Access-class with new VRF."  |
| AOS-22597 | If a CA profile is removed while SIP TLS calls using that profile are active, BYE messages will not be sent for any of those active calls.   |
| AOS-20871 | Receiving an initial INVITE with SDP that contains both audio and T.38 media descriptions will result in the call being on hold.   |
| AOS-10594 | In AOS R10.4.0 and higher, modem-passthrough will fail to send a reINVITE to G.711 if the endpoint is configured with a codec-list that does not contain G.711.  |
| AOS-10216 | The command "ip mgcp qos dscp <value>" will not take effect until either "ip mgcp" is disabled and then enabled or until the AOS device is reset.  |
| AOS-7738  | When the SIP-server monitor clears the primary SIP server from a delayed state due to a failure of the secondary SIP server, there will be a sixty second delay until a SIP registration is attempted to the primary SIP server. This delay will not occur if the SIP-server monitor is clearing the secondary SIP server from a delayed state due to a failure of the primary SIP server. |
| AOS-6995  | On the 3rd Gen. Total Access 900e and NetVanta 6250, SIP must be enabled in the running configuration whenever MGCP is used for voice.   |
| AOS-1136  | If an ADTRAN unit is configured with single call appearance mode, forwarded calls on a PRI trunk will fail.  |

---

|          |   |
|----------|---|
| AOS-1120 | Receiving a 183 after a 183 on hairpin calls when using media anchoring could result in no early media if the SDP in the second 183 differs from the first.                                 |
| AOS-1115 | Echo cancellation is not enabled on 3-way calls when using the local conferencing feature.  |
| AOS-1036 | With the ADTRAN unit set for voice flashhook mode transparent, the conference originator must wait for the third party to answer before executing the flashhook to initiate the conference. |

## 6. System Notes

Beginning with AOS version 17.09.01, the syntax of certain commands was modified from previous AOS versions by either removing or adding the **ip** keyword. In general, when the **ip** keyword appears in a command, it signifies that the command is only applicable to IPv4 functionality. As more features introduce IPv6 support, the **ipv6** keyword is added to signify the command is only applicable to IPv6 functionality. The **ip** keyword has been removed from several commands to signify that the command has both IPv4 and IPv6 functionality.

Due to this syntax change, downgrading a unit configured in AOS version R14.3.1.HA to a previous AOS version, could cause service disruption because the new syntax might not be recognized by the previous version. Upgrading a unit from an older AOS version to AOS version R14.3.1.HA will cause no service disruption because both the old and the new syntaxes are accepted. For more information on specific commands, refer to the [AOS Command Reference Guide](https://supportcommunity.adtran.com) available at <https://supportcommunity.adtran.com>.

It is recommended that your browser's cache be cleared before viewing the GUI after an upgrade.

MGCP is not supported on the NetVanta 6360.

As of R14.3.0 (or earlier), a valid SBC call capacity license is required for SIP B2BUA functionality on the following products:

- NetVanta 3140
- NetVanta 3148/4148
- NetVanta 6250
- Total Access 900e (third generation)



## 7. Upgrade Instructions

Upgrading Adtran products to the latest version of AOS firmware is explained in detail in the configuration guide [Upgrading Firmware in AOS](https://supportcommunity.adtran.com), available at <https://supportcommunity.adtran.com>.