



RELEASE NOTES

AOS Converged Access
AOS version R11.6.0.SA
April 17, 2015

Trademarks

Any brand names and product names included in this manual are trademarks, registered trademarks, or trade names of their respective holders.

To the Holder of the Manual

The contents of this manual are current as of the date of publication. ADTRAN reserves the right to change the contents without prior notice.

In no event will ADTRAN be liable for any special, incidental, or consequential damages or for commercial losses even if ADTRAN has been advised thereof as a result of issue of this publication.

Toll Fraud Liability

Be advised that certain security risks are inherent in the use of any telecommunications or networking equipment, including but not limited to, toll fraud, Denial of Service (DoS) attacks, loss or theft of data, and the unauthorized or illegal use of said equipment. ADTRAN OFFERS NO WARRANTIES, EITHER

EXPRESSED OR IMPLIED, REGARDING THE PREVENTION, DETECTION, OR DETERRENCE OF TOLL FRAUD, NETWORKING ATTACKS, OR UNAUTHORIZED, ILLEGAL, OR IMPROPER USE OF ADTRAN EQUIPMENT OR SOFTWARE. THEREFORE, ADTRAN IS NOT LIABLE FOR ANY LOSSES OR DAMAGES RESULTING FROM SUCH FRAUD, ATTACK, OR IMPROPER USE, INCLUDING, BUT NOT LIMITED TO, HUMAN AND DATA PRIVACY, INTELLECTUAL PROPERTY, MATERIAL ASSETS, FINANCIAL RESOURCES, LABOR AND LEGAL COSTS.

Ultimately, the responsibility for securing your telecommunication and networking equipment rests with you, and you are encouraged to review documentation regarding available security measures, their configuration and implementation, and to test such features as is necessary for your network.

ADTRAN Technical Support Community

For information on installing and configuring ADTRAN products, visit the ADTRAN Support Community, <https://supportforums.adtran.com>.



Pre-Sales Technical Support
(800) 615-1176
application.engineer@adtran.com

Corporate Office
901 Explorer Boulevard
P.O. Box 140000
Huntsville, AL 35814-4000
Phone: (256) 963-8000
www.adtran.com

Post-Sales Technical Support
(888) 423-8726
support@adtran.com

Copyright © 2015 ADTRAN, Inc.
All Rights Reserved.

Contents

<i>Introduction</i>	4
<i>Supported Platforms</i>	4
<i>System Notes</i>	5
<i>Features and Enhancements</i>	5
<i>Fixes</i>	6
<i>Errata</i>	12
<i>Upgrade Instructions</i>	17
<i>Documentation Updates</i>	17

Introduction

AOS version R11.6.0.SA is a major system release that adds new features and addresses customer issues that were uncovered in previous code releases.

This release is generally available code. Results obtained during internal testing have been evaluated and the code has been determined to be ready for general availability. Caveats discovered during testing but not addressed in this build are listed in [Errata on page 12](#).

A list of new or updated documents for this release appears in [Documentation Updates on page 17](#).

Configuration guides, white papers, data sheets, and other documentation can be found on ADTRAN's Support Forum, <https://supportforums.adtran.com>. The contents of these release notes will focus on the platforms listed below.

Supported Platforms

The following platforms are supported in AOS version R11.6.0.SA. To confirm the Boot ROM version of the ADTRAN unit, Telnet or console to the unit and issue the **show version** command. In the command output, the Boot ROM version will be listed as **Boot ROM version XX.XX.XX**. If you require a Boot ROM upgrade, please contact ADTRAN Technical Support (support@adtran.com or 888-423-8726) for assistance.

Platform	Standard Feature Pack	Enhanced Feature Pack	SBC Feature Pack	Minimum Boot ROM
NetVanta 644		√		A5.01.B1
NetVanta 1335		√		15.01.00
NetVanta 3120		√		14.04.00
NetVanta 3130		√		14.04.00
NetVanta 3140	√	√		R11.5.0
NetVanta 3200/3205 (3rd Gen. only)	√	√		17.02.01.00
NetVanta 3305 (2nd Gen. only)	√	√		04.02.00
NetVanta 3430	√	√		13.03.SB
NetVanta 3430 (2nd Gen.)	√	√	√	17.05.01.00
NetVanta 3448	√	√	√	13.03.SB
NetVanta 3450	√	√		17.06.01.00
NetVanta 3458	√	√		17.06.01.00
NetVanta 4305 (2nd Gen. only)	√	√		08.01.00
NetVanta 4430	√	√	√	17.04.01.00
NetVanta 4660		√		R10.10.0
NetVanta 5305	√	√		11.03.00
NetVanta 5660		√		R11.4.0
NetVanta 6240		√	√	A5.01.00
NetVanta 6250		√	√	R10.9.0
NetVanta 6310/6330		√	√	A3.01.B2
NetVanta 6355		√	√	14.06.00
NetVanta 6360		√		R11.2.0

Platform	Standard Feature Pack	Enhanced Feature Pack	SBC Feature Pack	Minimum Boot ROM
NetVanta 6410			√	R11.3.0
Total Access 900 Series (2nd Gen. only)		√		14.04.00
Total Access 900e Series (2nd Gen. only)		√	√	14.05.00.SA
Total Access 900e Series (3rd Gen. only)		√	√	R10.9.0

System Notes

- Beginning with AOS version 17.09.01, the syntax of certain commands was modified from previous AOS versions by either removing or adding the **ip** keyword. In general, when the **ip** keyword appears in a command, it signifies that the command is only applicable to IPv4 functionality. As more features introduce IPv6 support, the **ipv6** keyword is added to signify the command is only applicable to IPv6 functionality. The **ip** keyword has been removed from several commands to signify that the command has both IPv4 and IPv6 functionality.

Due to this syntax change, downgrading a unit configured in AOS version R11.6.0.SA to a previous AOS version, could cause service disruption because the new syntax might not be recognized by the previous version. Upgrading a unit from an older AOS version to AOS version R11.6.0.SA will cause no service disruption because both the old and the new syntaxes are accepted. For more information on specific commands, refer to the [AOS Command Reference Guide](https://supportforums.adtran.com) available at <https://supportforums.adtran.com>.

- It is recommended that your browser's cache be cleared before viewing the GUI after an upgrade.
- MGCP is not supported on the NetVanta 6360.

Features and Enhancements

This section highlights the major features, commands, and behavioral changes for all Converged Access products running AOS version R11.6.0.SA.

- Added the ability to change the state of the status LED on the NetVanta 4660 and 5660 via CLI commands.
- Added the ability for the NetVanta 4660 and 5660 to send dying gasp SNMP traps.
- Added support for the ADTRAN WiFi Access Controller in the NetVanta 4660, 5660, and 6360.
- Added an over-temperature protection feature to the NetVanta 4660 and 5660 that allows the unit to reboot into a low power mode if the internal temperature exceeds the safe operating range. This feature also allows the unit to reboot into a normal state after a configured cooling off period.
- Added the ability for the NetVanta 4660 and 5660 to send dying gasp EOC messages when using the SHDSL and VDSL Carrier Ethernet modules.

This section highlights the Carrier Ethernet specific features, commands, and behavioral changes available in products running AOS version R11.6.0.SA.

- Added the ability to apply multiple shapers to a single queue to allow hierarchical QoS configurations.
- Added the ability to specify multiple CE VLAN IDs as either a list or range of VLANs for matching in an EVC map.

- Added the ability to globally change the EtherType to be used for the CE VLAN ID from the default of 0x8100 with the **ethernet ce-vlan-tpid** command. Additionally, the **no ce-vlan-tpid** command was added to EVC maps to restore the default of 0x8100 for a given EVC map.
- Added support to E-LMI to track the status of Y.1731 MEPs and EFM group bandwidth to determine the EVC status that should be provided out a UNI via E-LMI.
- Added single-ended Y.1731 ETH-LM functionality for point-to-point services.
- Added the ability to save Y.1731 performance monitoring data per MEF 35 to | separated files on time intervals.
- Added the ability to pass jumbo frames up to 9200 bytes on Layer 2 services.
- Added a global command (**unknown-unicast limit <rate>**) to limit the rate at which unknown unicast frames are forwarded when MAC learning is enabled.

This section highlights the Voice specific features, commands, and behavioral changes available in products running AOS version R11.6.0.SA.

- Added IPv6 SIP and RTP support to the NetVanta 6250, 6360, and the Total Access 900e (third generation).
- Added the ability for the SIP proxy to fork calls to SCA users registered with unique extensions while in survivability mode. Previously forking in survivability mode was only possible if all users in a SCA registered with the same extension.
- When registration rate pacing is enabled, the SIP proxy will now track the egress interface towards the soft switch, and if the egress interface changes, the next REGISTER from the phone will be allowed through. This improves the capabilities of the SIP proxy in configurations with multiple WAN connections.
- The SIP Server Monitor Recovery Delay feature was enhanced so that when a recovery attempt fails for a particular server, the penalty box timer restarts for that server instead of going into a continuous recovery attempt state.

Fixes

This section highlights major bug fixes for all products running AOS version R11.6.0.SA.

- On the NetVanta 3140, 4660, 5660, 6250, 6360 and the Total Access 900e (third generation), issuing the **show ip flow top-talker hour detail** resulted in a reboot.
- When running AOS R11.4.2 in some configurations with multiple VAPs, NetVanta 150s could not be controlled.
- In certain cases, NetVanta 150s could not be controlled by devices running AOS R11.4.2.
- When rebooting a NetVanta 6310 or 6330 running AOS R11.4.2, the connection between an EVC and the EFM group could not be restored. An error stating **%Error finding interface efm-group 1** was displayed, and the EVC was non-functional due to the missing connection to the EFM group.
- Wi-Fi multimedia (WMM), configured with the command **qos-mode wmm**, is not supported on NetVanta 150 Access Points and the configuration commands have been removed.
- During a SNMP denial of service attack, an out of memory reboot may have occurred.
- On the NetVanta 3120, 3130, 3448, and 3458, when traffic was flowing over one port in a channel group, if that port went down, the port-channel bounced.

- On the NetVanta 3120, 3130, 3448, and 3458, removing and then re-adding ports to a port channel resulted in frames being looped between those ports.
- In AOS R11.5.1, routing performance on the NetVanta 3448 had decreased by roughly 27 percent compared to R11.5.0.
- In AOS R11.5.1, routing performance on the NetVanta 3305 had decreased by roughly 9 percent compared to R11.5.0.
- Resolved a potential lockup when under a SSH denial of service attack with AAA configured.
- If an ECDSA or ED25519 key (both of which are unsupported) was presented to the SSH server, a **Bad string length** error was returned instead of proceeding with the remaining authentication options.
- Unsupported SSH authentication methods (e.g., null) were improperly treated as authentication failures instead of unsupported methods.
- The WEP configuration options were removed for the NetVanta 160 Access Points.
- Application of a MAC ACL to an access point did not persist through reboot.
- On the NetVanta 6310 and 6330 with an EFM module installed, the output of **show mef evc-map** command improperly listed **MEN C-tag** and **MEN C-tag Pri** values. The NetVanta 6310 and 6330 do not support adding a C-tag.
- On the NetVanta 6310 and 6330 with an EFM module installed, two EVC maps that differed only by the matched DSCP value could not be configured, even though that configuration is supported.
- When connecting to a unit with SSH, if a long login banner was configured the **--MORE--** prompt was presented.
- New temporary DH key pairs were not generated for each TLS connection when using DHE ciphers with the HTTPS server, SMTP client, Auto-Link client, Auto Config client, HTTPS packet capture export, and the **copy https** command.
- Exporting a packet capture to flash memory resulted in audio loss while the file was being written to flash.
- On the NetVanta 3140, if the speed of a Gigabit Ethernet port was statically set to 100 or 1000 Mbps, and then the speed was changed to another value, a reboot may have been required before traffic could pass.
- Issuing the **test if interface switchport <slot/port>** or the **test if interface xgigabit-switchport <slot/port>** commands on a track resulted in a reboot. These commands are invalid without the **line-protocol** parameter at the end (e.g., **test if interface switchport <slot/port> line-protocol**).
- When using the **show interface ppp 1 realtime** command, the input and output rates were incorrect if **statistics rate-interval** was set to a value that was not divisible by 60.
- On the NetVanta 6310 and 6330, when a SHDSL ATM or SHDSL EFM module was installed, the **show interface shdsl x/1 version** command was missing.
- If a NetVanta 6310 or 6330 with a SHDSL EFM module installed received a malformed version management packet, a reboot may have occurred.
- An AOS configuration file larger than 256 KB could not be backed up to n-Command MSP.
- When attempting to view the Physical Interfaces page in the GUI of a NetVanta 5305 with a DS3 module installed, a 503 Service Unavailable error was presented to the user.
- The NetVanta 644 failed to receive 802.1q tagged packets with an IP payload between 1497 and 1500 bytes.
- In rare cases, DNS queries created by an AOS device were sent using a source port that was already in use by another local service (e.g., SIP), which prevented DNS responses from being properly received.

- To address the SSL 3.0 POODLE vulnerability, SSL 3.0 has been disabled by default for the HTTPS server, SMTP client, Auto-Link client, Auto Config client, HTTPS packet capture export, and the **copy https** command. To enable SSL 3.0 support, an **allow-ssl3** parameter has been added to all of these clients and servers, with the exception of Auto-Link.

Additionally, SSL 2.0 has been disabled in all of the previously mentioned clients. It was already disabled by default for the HTTPS server.

- On the NetVanta 6410, a cold boot resulted in a warm start SNMP trap being sent.
- When viewing the Physical Interfaces page in the GUI on a unit with a T1 configured, a 503 Service Unavailable message was presented.
- When accessing the GUI using HTTPS, cookies were sent without the **secure** attribute set.
- SNMP communities containing the @ character were not accepted on products with switchports.
- The following OpenSSL security vulnerabilities were resolved:
 - SSL/TLS MITM vulnerability (CVE-2014-0224)
 - Anonymous ECDH denial of service (CVE-2014-3470)
 - Information leak in pretty printing functions (CVE-2014-3508)
 - Crash with SRP ciphersuite in Server Hello message (CVE-2014-5139)
 - Race condition in ssl_parse_serverhello_tlsextr (CVE-2014-3509)
 - OpenSSL TLS protocol downgrade attack (CVE-2014-3511)
 - ECDHE silently downgrades to ECDH [Client] (CVE-2014-3572)
 - RSA silently downgrades to EXPORT_RSA [Client] (CVE-2015-0204)
 - Bignum squaring may produce incorrect results (CVE-2014-3570)
- Issuing the **crypto ca enroll** command resulted in the terminal length being set to 0.
- Rebooting a NetVanta 160 after editing an associated MAC access list caused the AP to transmit SSID **Wireless11**.
- The formatting of LLDP debug was improved to make it easier to read and consistent with other AOS debugs.
- The **show interface dot11ap <number>** command may have shown an incorrect radio channel for a NetVanta 160.
- The GUI of a NetVanta device acting as a wireless access controller could not display the software currently running on a connected access point.
- An AOS device displayed an event message in the CLI reporting a successful NetVanta 160 software upgrade, even if the upgrade had failed.
- The command **boot config flash <filename>** did not function properly on many AOS platforms.
- In some cases, a host name entry in an ACL failed to resolve to the correct IP address even though the router's host table reflected the correct IP address.
- The GUI did not produce an error when VLANs were selected for a particular VAP when encapsulation 802.1q was not enabled.

This section highlights the Carrier Ethernet specific bug fixes in products running AOS version R11.6.0.SA.

- With a large number of EVCs configured, ELMI would not send all configured EVCs in a Full Status Message.
- If a queue shaper was created followed by a port shaper and the port shaper was subsequently removed or shut down, then the queue shaper could not be properly removed or shut down.
- The help text for the **ethernet y1731 linktrace-cache hold-time** and **ethernet y1731 linktrace-cache size** commands was incorrect.
- If two EVC maps were identical except for the connected EVC, both entered the running state improperly instead of both being disabled.
- Entering an invalid character in a **connect men-port** or **connect uni** statement on an EVC caused the EVC to malfunction.
- The CLI allowed configuration of multiple MEN port connections to a MAC switched EVC. This configuration is not supported.
- The **service double-tagged s-tag <id> c-tag <id>** command was listed as an option for Y.1731 MEGs, but is not actually supported.
- ifUnknownProtos in the ifTable reported **0** instead of **not available** for SHDSL interfaces.
- If 802.3ah link OAM was enabled on an interface, issuing the **show ethernet oam discovery** or **show ethernet oam statistics** commands and pressing **Enter** to display additional lines resulted in misalignment of the CLI.
- In rare cases, a reboot occurred on the NetVanta 4660, NetVanta 5660, and NetVanta 6360.

This section highlights the Voice specific bug fixes in products running AOS version R11.6.0.SA.

- When running AOS R11.4.2, the local conferencing feature did not work.
- When a call was placed on hold by an analog user and then retrieved, an RTP resource may have been leaked.
- In rare cases a reboot occurred while the SIP proxy was processing a SIP message.
- When an FXS port was configured to use ground start and an inbound call rang but was not answered, the FXS port would not ground the tip again or send ring voltage on future calls.
- In AOS R11.4.2, dial tone detection on FXO ports failed on the NetVanta 6250, 6360, and Total Access 900e (third generation).
- If a TDM-to-SIP call was in a PreConnected state due to receiving 183 Session Progress message, audio would only flow in the SIP-to-TDM direction, which prevented interaction with some IVRs and voicemail systems.
- When running AOS R11.5.0 and higher, FQDNs configured on SIP trunks, VQM reporters, **voip name-service host** entries, the SIP proxy in stateful mode, and MGCP that rely on SRV records will fail if the transport in use is not TLS.
- The **rtp media** command set on SIP trunks was not present on the NetVanta 3430, 3448, 4430, and 6410 SBCs.
- When an ISDN timeout occurred on a SIP-to-ISDN call, the unit sent a 400 Bad Request response instead of the more appropriate 408 Request Timeout response.

- If media anchoring was being used on a call that received multiple reINVITEs, the ports listed in SDP may have changed without incrementing the sess-version.
- The **t38 cng-relay-selective** command did not function properly on the NetVanta 6250, 6360, or Total Access 900e (third generation).
- In rare cases, a response received by the SIP proxy caused a reboot.
- Receiving early media SDP on a call that resulted in hairpin media and also required DTMF transcoding resulted in the call failing to connect and being torn down immediately.
- SIP packet capture functionality was modified so that calls are only tracked when the packet capture is both enabled and attached to at least one interface.
- The LocalURI and RemoteURI fields in VQM PUBLISH messages were reversed for calls in the SIP-to-TDM direction.
- On the NetVanta 6250, 6360, and Total Access 900e (third generation), DTMF tones that were shorter than the minimum valid digit requirement were still being qualified as valid digits.
- When using SIP TLS, during the TLS handshake process a very small amount of memory leaked. This occurred when the device was acting as a TLS client or when the device was acting as a TLS server and mutual authentication was enabled. If a large number of connections were created, a reboot eventually occurred.
- If a call on a voice loopback account received a reINVITE, audio was no longer be looped. If no reINVITE was received, the voice loopback account functioned normally.
- Accessing the Voice > System Parameters or Voice > VoIP Settings menus in the GUI resulted in a 503 Service Unavailable response.
- When using RTP firewall traversal, if the SIP device behind the AOS unit changed RTP ports in SDP and was slow to actually start using the new ports, the NAT session for the new RTP stream may have been unexpectedly removed. The **ip rtp firewall-traversal enforce-symmetric-port** command has been added to help in this scenario.
- When using optional SRTP, if a call was answered and SRTP could not be negotiated because there were no common cipher suites, a reboot occurred.
- The firmware image for the NetVanta 6410 did not include the .wav files for US ringback and silence that are included by default on the SBC products.
- When using SRTP with **ip rtp symmetric-filter** enabled, calls had one-way audio.
- After the first 18x provisional response was received on a SIP trunk call through the B2BUA, if additional 18x provisional responses were received, they were not relayed to another SIP or ISDN trunk.
- With transcoding enabled, if a SIP-to-SIP call through the B2BUA that originally did not require transcoding was reINVITED to a CODEC that required transcoding, and was then reINVITED again, the transcoding media anchoring session may not have been removed, resulting in two RTP streams being transmitted.
- The GUI allowed the SNMP link status traps to be enabled/disabled for FXS and FXO interfaces, but the change could not be saved.
- Calls initiated via a loopback account could not be placed if they matched a dial plan entry that ended in \$.
- If a **conferencing-uri** was configured on a voice trunk, AOS attempted to resolve the configured value.
- When using SIP proxy user templates, in some cases the Request-URI of inbound INVITEs was improperly modified.

- On a SIP trunk to SIP trunk call, if a SIP 488 response was received on one trunk, that response was not sent out the other trunk. Instead a 400 Bad Request response was sent out the other trunk.
- When using the SIP proxy, if a Remote-Party-ID header was improperly formatted, the SIP message containing the header was not proxied.
- In certain call transfer scenarios where the IP PBX tries to remove itself from the RTP path and then reinsert itself, a no audio condition was encountered.
- When using VQM reporter, the Gap Duration (GD) reported in the BurstGapLoss values was greater than 3,600,000, which is the maximum value allowed by RFC 6035.
- Received SDP offers containing a rejected audio media stream as well as an image media stream were not handled properly. In this scenario, the audio media was preferred and the image media was ignored resulting in erroneous behavior.
- When generating an SNMP trap for a SIP proxy rollover, the wrong OID was used for adSipProxyRollover.
- On the NetVanta 6250 and Total Access 900e (third generation) with MGCP configured, harmless pthread messages were seen on the console during boot up. They were also seen when adding or deleting IP routes that caused the MGCP endpoints to restart.
- The detailed voice quality statistics for a call did not accurately reflect the adjustments made by modem passthrough.
- On the NetVanta 6250 and Total Access 900e (third generation), the **timing-source internal** command was not present.
- Within either a voice trunk or voice user with a CODEC list configured, entering **no codec-list** *<list name>* *<direction>* always removed the *<list name>*, no matter what the configured direction actually was.

Errata

The following is a list of errata that still exist in all products running AOS version R11.6.0.SA.

- Errors are displayed when the **no shutdown** command in EVC configurations is restored while booting a NetVanta 6310 or 6330. These errors are purely cosmetic.
- After configuring the privilege level of exec commands, those commands will not be set to the proper privilege level unless the configuration is saved and the unit rebooted or any **no privilege** command is issued.
- On the NetVanta 6410, HTTP file transfers to the unit's flash memory can be up to 10 times slower than TFTP.
- If a track is configured to monitor the line protocol of an interface configured for 802.1q, the track will never go into a passing state even the interface is up. This issue does not affect the NetVanta 4660, 5660, or 6360. **Workaround:** Track the line protocol of the subinterface.
- Copying a file larger than 16 MB from flash memory of an AOS device via HTTP/HTTPS (including using Auto-Link) will fail.
- In some command sets, the **exit** command is not visible even though it still functions properly.
- On the NetVanta 5305, VPN performance for 64 and 256 byte packets decreased moderately compared to R11.2.0.
- Speed and duplex settings are displayed with on MEF Ethernet interfaces in **show running-config verbose** command output, even though those options are not valid and cannot be configured for that type of interface.
- In the VQM RTP Monitoring menu, the refresh button refreshes the displayed graphic, but it also duplicates information in the lower part of the menu. In addition, when the cursor hovers over a data point, multiple instances of the same data display.
- In the VQM RTP Monitoring menu, the Source IPs and Interfaces menus have invisible data points that appear and display data when the cursor hovers over them. The invisible data point information duplicates a visible data point and can usually be found hidden above the visible data point.
- The output of **show qos map interface <interface>** shows **ce-vlan-id** instead of **vlan-id** and **ce-vlan-pri** instead of **cos** on products other than the NetVanta 4660.
- On the NetVanta 6240, SNMP traps for warm start and cold start are reversed.
- On a NetVanta 4430, information for an inserted SFP does not display correctly.
- Ethernet interfaces in third generation Total Access 900e units are not visible in the Data > IP Interfaces GUI menu. These interfaces are visible and can be configured from the System > Physical Interfaces menu instead.
- Configuring a NetVanta 160's channel setting to **least-congested** may not properly adjust to the least congested channel available.
- The Total Access 900e (third generation) and NetVanta 6250 send a cold start SNMP trap on reload instead of a warm start trap.
- On the NetVanta 6250 and Total Access 900e Series (third generation), when running a large amount of traffic across a VPN tunnel with crypto FFE disabled, the unit will occasionally reboot citing a memory issue. Enabling the **ip crypto ffe** command prevents this reboot from occurring and is the desired setting when configuring VPN due to the performance increase of the FFE functionality.

- On very rare occasions, port T1 3/3 on an Octal T1 NIM can stop negotiating LCP when it is part of an MLPPP bundle. Rebooting the device will restore the interface.
- On the NetVanta 6310 or 6330, if a SHDSL circuit with a detected bad splice retrains to a different line rate, the distance of the bad splice will display incorrectly.
- On the NetVanta 6310 or 6330, if the top level ATM interface on a SHDSL ATM NIM2 module is disabled and re-enabled, the ATM circuit will no longer be able to pass traffic. The ADTRAN unit must be rebooted to correct the problem.
- When using a T1/E1 EFM NIM2 in the NetVanta 6310 or 6330, the EFM counters do not increment as traffic passes through the device.
- With the SHDSL ATM NIM2, the NetVanta 6310 and 6330 drop approximately 1 out of every 15K packets from the SHDSL to Ethernet direction.
- Removing a USB modem from the USB NIM while active could cause the AOS device to reboot. Shutting down the demand interface being used by the modem prior to removing the modem will prevent this reboot.
- Event messages indicating a firmware upgrade was attempted may appear in the AOS event log for NetVanta 160 APs that are not being upgraded.
- Having more than two entries in a Network Monitor ICMP probe test list will display **Tracked by: Nothing** in the **show probe** command output. This is merely a display error; the probes still function correctly.
- Accessing the GUI via HTTPS may be slow.
- VQM may show a loopback interface in the GUI when a loopback interface is not configured.
- The VNS verification process does not remove inconsistent A-type records from the host table after the configured number of attempts.
- If the **ethernet-cfm** command is configured on a MEF Ethernet interface, the output of the following CLI commands is not formatted properly:
 1. **show ethernet cfm association**
 2. **show ethernet cfm stack**
 3. **show ethernet cfm mep local**
 4. **show ethernet cfm mep local detail**
- The **called-number** command on a demand interface does not function properly.
- When using XAUTH with a VPN client, an AOS device requests CHAP authentication from the client but does not send a CHAP challenge payload. This can cause issues with VPN clients that expect to receive this payload.
- If a USB modem is physically disconnected from a USB WWAN NIM while active NIM is active, the demand interface being used by the modem will not automatically shut down. The demand interface should be disabled before removing the modem to prevent this issue.
- On the NetVanta 6310/6330, with FFE enabled, passing traffic from the Ethernet 0/1 interface out an Ethernet NIM2 can cause the Ethernet 0/1 interface to fail. The interface is recovered with a reboot. Disabling FFE on the Ethernet 0/1 interface prevents the issue.
- An SNMP walk of the NetVanta 6355 lists the physical address for the first interface index only.

- The current AOS implementation of DHCP message construction can result in Windows XP machines not adopting the DNS servers defined within the DHCP offer. A workaround using a numbered IP/hex option will allow the message to be constructed in a manner that Windows XP will accept. Microsoft also offers a hotfix to resolve this Windows issue.
- The system clock may drift and lose synchronization with higher stratum devices when NTP is enabled. This issue only affects the NetVanta 3448, 3458, and 6240 products.
- The **vap-reference** command will not replicate VLAN IDs for an AP unless 802.1q encapsulation has been manually enabled on the AP expecting to receive the replicated configuration.
- Updating PRL values on a Sprint NetVanta 3G NIM may not function properly.
- In rare cases, when an IP PBX and IP phones are both passing through NAT and the SIP proxy on an AOS device, some call flows can enter a one-way audio state. **Workaround:** Enable the **ip rtp firewall-traversal enforce-symmetric-ip** command from the Global Configuration mode.
- A large enough drift in the system clock can cause an error when the NTP server attempts to synchronize.
- On a NetVanta 1335, a switchport that is configured as a port channel cannot change the edge port mode and cannot be changed from a port channel to another configuration using the GUI.
- The **show interfaces** command output for multilink Frame Relay interfaces will display an incorrect available bandwidth value when a physical link residing in the bundle is down.
- The **show atm pvc** counters do not increment.
- The GUI statistics page for the SHDSL interface does not refresh when in 4-wire mode.
- The GUI shows invalid line rate options for a SHDSL interface in 2-wire mode.
- The GUI line rate options for a SHDSL interface do not match those of the CLI.
- Configuring a port channel on a NetVanta 3448 can cause the STP topology to become unstable.
- Sierra Wireless USB305 3G modems are sometimes not recognized by the NetVanta USB WWAN NIM.
- Changing the route metric value using **ipv6 address autoconfig default metric <value>** command does not change the administrative distance of the default route.
- The NetVanta 5305 can drop some traffic prioritized by class-based weighted fair queuing (CBWFQ) on a MLPPP interface when a stand-alone QoS map is applied.
- A NetVanta 5305 can stop passing traffic for brief intervals when negotiating frequent VPN tunnels using Diffie Hellman Group 5.
- The output queue statistics on an Ethernet interface can fail to display output queue drops when FIFO is enabled.
- Prioritized traffic can be dropped at a significant rate on PPP interfaces when using a parent QoS map (that references a child map with priority allocation), if the shaped rate is configured for more than 75 percent of the line rate.
- If the **bandwidth remaining percent** command is used in a QoS map, the CLI does not display the correct value for Required Bandwidth in the event message generated by applying a QoS map.
- EAP Identity Responses from a wireless client that do not contain an Identity field can result in the NetVanta 150 creating a malformed RADIUS packet.
- NetVanta 150s may not properly handle immediate Access-Accept responses to Access-Request messages.
- 3G connections using a NetVanta USB WWAN NIM and a Sierra Lightning modem can fail.

- The name of a deleted IPv4 ACL cannot be used to name a new IPv6 ACL.
- The cellular interface can trigger a core dump on a NetVanta 3448 when changing states.
- Browsing to the Switchports menu from the Port Security menu on the NetVanta 1335 WiFi GUI results in a 503 Service Unavailable error.
- A Spanning Tree L2 broadcast storm lasting several hours can cause the NetVanta 1335 to reboot.
- The pass phrase for the Wireless Wizard does not persist across reboots.
- When a switchport on a NetVanta 3458 is configured for **port-security**, it does not receive BPDUs. If multiple connections between the NetVanta 3458 and another switch are made, a switching loop could occur because both ports will automatically enter a forwarding state even though the Spanning Tree protocol should cause one port to enter a blocking state.
- Using the command **debug ethernet cfm loopback request domain** <domain name> to filter Ethernet CFM loopback debugs may not display the debug output to the console. Removing the filter and using the **debug ethernet cfm loopback request** command will function properly.
- The output of the command **show ethernet cfm mep local** may display an incorrect maintenance association for a MEP ID if multiple maintenance associations are configured on the unit.
- The NetVanta 6240 should send warm_start SNMP traps when the unit is told to reboot by software. It should only send cold_start traps when the power is cycled. Instead, it is sending cold_start traps, even when reloaded by software.

The following is a list of Carrier Ethernet specific errata that exist in products running AOS version R11.6.0.SA.

- If a configuration with 200 EVCs, 200 EVC maps, and 200 Y.1731 MEPs is loaded and the MEPs are entered into the configuration before the EVC maps, the MEPs will not function properly. **Workaround:** Configure the EVC maps before the Y.1731 MEPs.
- Issuing **shutdown** followed by **no shutdown** on an EVC configured for MAC switching will cause the other EVCs connected to the same EFM group to become MAC switched even if those EVCs are not configured for MAC switching. This issue is resolved by a reboot.
- An up MEP configured on a UNI in an E-TREE topology will not function properly.
- On the NetVanta 6360, in rare cases a reboot may be seen when a VDSL Carrier Ethernet module is installed.
- If an EVC is added while the unit is the process of sending an ELMI FULL status continued message, the data instance (DI) bit is not incremented and the EVC is not added.
- The **efm-group** interface type option is missing from the **cross-connect** command on PPP interfaces.
- The **efm-group** interface type option is missing from the **tunnel source** command on tunnel interfaces.
- When using a SHDSL module, frame counts for broadcast and multicast traffic may not increment on the parent EFM group interface. The subinterface counters do properly increment.

The following is a list of Voice specific errata that exist in products running AOS version R11.6.0.SA.

- If a caller ID name longer than 256 characters is placed into a P-Asserted-Identity header, a reboot will occur.
- TLS negotiation will fail when using ECDSA ciphers for SIP TLS.

- If an INVITE is received that has a caller ID name that is 158 characters or longer and debug is enabled, a reboot will occur.
- When using T.38, if a page transmission lasts longer than the configured value of the **ip rtp session timeout** command (45 seconds by default) and a reINVITE is received, the fax will fail. **Workaround:** Increase the value of **ip rtp session timeout** to 120 seconds.
- On the NetVanta 6250, 6360, and Total Access 900e (third generation), if a call negotiates to a 40 ms packetization period, which is not supported on those platforms, a reboot will occur when processing in-call DTMF.
- Removing a voice trunk while calls are active may result in the unit rebooting.
- Issuing the command **clear voice call active** with active MGCP calls may result in a reboot.
- If **sip tls** is configured while **sip** is disabled, **no sip tls** must be issued before **sip** can be enabled, otherwise the following error will be displayed: %Error: Failed to modify SIP Access-class with new VRF.
- If mandatory SRTP is configured on a voice trunk, calls will still be established if SRTP is not received in the SDP answer.
- If a CA profile is removed while SIP TLS calls using that profile are active, BYE messages will not be sent for any of the active calls.
- The ERL tool is not functional on the NetVanta 6360.
- On the NetVanta 6360, if the onboard FXO port is configured to receive digits, a 500 ms delay is required after answering before receiving the first DTMF digit.
- Call waiting caller ID does not function properly on the NetVanta 6240.
- Receiving an initial INVITE with both audio and T.38 SDP will result in the call being placed on hold.
- On the Total Access 900e Series (third generation) and NetVanta 6250 Series, if the second CODEC listed in the MGCP Local Connection Options is not one of the CODECs defined in the CODEC list assigned to the MGCP endpoint, the unit will respond with 534 Transaction Failed response resulting in a failed call.
- In AOS R10.4.0 and higher, modem-passthrough will fail to send a reINVITE to G.711 if the endpoint is configured with a codec-list that doesn't contain G.711.
- The command **ip mgcp qos dscp <value>** will not take effect until either **ip mgcp** is disabled and then re-enabled or the AOS device is reset.
- When the SIP server monitor clears the primary SIP server from a delayed state due to a failure of the secondary SIP server, there will be a 60-second delay until a SIP registration is attempted to the primary SIP server. This delay will not occur if the SIP server monitor is clearing the secondary SIP server from a delayed state due to a failure of the primary SIP server.
- On the Total Access 900e (third generation) and NetVanta 6250, SIP must be enabled in the running configuration whenever MGCP is used for voice.
- Invalid characters are allowed in a host name for the SIP server on a voice trunk.
- On the Total Access 900e (third generation) and NetVanta 6250, if the remote voice gateway changes the SSRC in an RTP stream received by the AOS unit, and the sequence numbers are not contiguous, VQM and the output of the **show voice quality-stats** command will log lost packets for the number of packets between the last sequence number of the first stream and the first sequence number of the new stream. The output of **show voice quality-stats <ID>** will also not reflect that the SSRC value changed on the call.

- When G.729 Annex B is negotiated and VAD is enabled on the endpoint(s) involved in the call, the unit will generate comfort noise packets with payload type 13. This can cause issues with devices expecting comfort noise packets to have the same payload type as RTP (18). However, payload type 13 is specified in the SDP from the AOS device.
- If an ADTRAN unit is configured with single call appearance mode, forwarded calls on a PRI trunk will fail.
- When using media anchoring, receiving a 183 Session Progress after a previous 183 on hairpinned calls can result in no early media if the SDP in the second 183 differs from the first.
- Echo cancellation is not enabled on three-way calls when using the local conferencing feature.
- On NetVanta 644 and NetVanta 6240 Series units, V.21 messages will sound overly amplified when listening to the TX output of a T.38 DSP capture. This is a flaw of the capture utility and does not represent how the audio actually sounds.
- DSP captures on the NetVanta 6240 and 644 platforms consume large amounts of memory while in progress. The unit could become unstable if a DSP capture is active for an unusually long period of time.
- With the ADTRAN unit set for **voice flashhook mode transparent**, the conference originator must wait for the third-party to answer before executing the flashhook to initiate the conference.
- On the NetVanta 6240 Series, over an extended period of use, T.38 calls can cause DSP channels to cease producing a dial tone and have poor voice quality. Rebooting the unit will correct the problem.
- NetVanta 6240 only: While running 29 or more simultaneous calls using E&M Immediate, Wink, or Feature Group D, it is possible to get in a state where DTMF tone detection will not function on any outbound (DSX to SIP) call using DSP 0/1.15 or higher. While in this failed state, all calls will continue to function in either call direction on DSP 0/2, as well as all calls on DSP0/1 in the inbound direction. With a load of 28 or less calls, all calls will function reliably in both directions on both DSPs. No consistent work around has been identified at this time. A unit reboot will typically solve the problem.
- The NetVanta 6240 Series IP business gateways can reboot if 60 simultaneous calls are placed through the DSP.
- The Total Access 900e Series (second generation) cannot properly handle more than 40 simultaneous E&M RBS calls. More than 40 simultaneously active calls could result in no dial tone or no audio on the last 8 channels.
- Using the HEAD acoustics test suite, some G.168 echo cancellation test cases fail on the NetVanta 6240 and NetVanta 644. These same tests pass on Total Access 900 Series units. There is no reason to believe this would affect a customer in the field.
- On the NetVanta 6310/6330 Series, if a SIP trunk is trying to register a large number of users and the registration fails, activating **debug sip trunk-registration** will cause the Telnet and console connection to become unresponsive. A reboot clears the condition.

Upgrade Instructions

Upgrading ADTRAN products to the latest version of AOS firmware is explained in detail in the configuration guide *Upgrading Firmware in AOS*, available at <https://supportforums.adtran.com>.

Documentation Updates

The following documents were updated or newly released for AOS version R11.6.0.SA or later. These documents can be found on ADTRAN's Support Forum available at <https://supportforums.adtran.com>.

You can select the hyperlink below to be immediately redirected to the document.

- [*AOS Command Reference Guide*](#)
- [*Carrier Ethernet Services in AOS*](#)
- [*SNMP in AOS*](#)
- [*Configuring Ethernet OAM for Y.1731*](#)
- [*Configuring SIP Proxy in AOS*](#)