
Adtran BSAP 3.7.1 & 4.1 vWLAN Patch Release Notes

Release Notes

6ABSAP37141P-40A

June 2022



To the Holder of this Document

The contents of this manual are current as of the date of publication. Adtran reserves the right to change the contents without prior notice.

Trademark Information

"Adtran" and the Adtran logo are registered trademarks of Adtran, Inc. Brand names and product names included in this document are trademarks, registered trademarks, or trade names of their respective holders.

Disclaimer of Liability

The information or statements given in this document concerning the suitability, capacity, or performance of the mentioned hardware or software products are given "as is", and any liability arising in connection with such hardware or software products shall be governed by Adtran's standard terms and conditions of sale unless otherwise set forth in a separately negotiated written agreement with Adtran that specifically applies to such hardware or software products.

To the fullest extent allowed by applicable law, in no event shall Adtran be liable for errors in this document for any damages, including but not limited to special, indirect, incidental or consequential, or any losses, such as but not limited to loss of profit, revenue, business interruption, business opportunity or data, that may arise from the use of this document or the information in it.

Be advised that certain security risks are inherent in the use of any telecommunications or networking equipment, including but not limited to, toll fraud, Denial of Service (DoS) attacks, loss or theft of data, and the unauthorized or illegal use of said equipment. ADTRAN OFFERS NO WARRANTIES, EITHER EXPRESSED OR IMPLIED, REGARDING THE PREVENTION, DETECTION, OR DETERRENCE OF TOLL FRAUD, NETWORKING ATTACKS, OR UNAUTHORIZED, ILLEGAL, OR IMPROPER USE OF ADTRAN EQUIPMENT OR SOFTWARE. THEREFORE, ADTRAN IS NOT LIABLE FOR ANY LOSSES OR DAMAGES RESULTING FROM SUCH FRAUD, ATTACK, OR IMPROPER USE, INCLUDING, BUT NOT LIMITED TO, HUMAN AND DATA PRIVACY, INTELLECTUAL PROPERTY, MATERIAL ASSETS, FINANCIAL RESOURCES, LABOR AND LEGAL COSTS. Ultimately, the responsibility for securing your telecommunication and networking equipment rests with you, and you are encouraged to review documentation regarding available security measures, their configuration and implementation, and to test such features as is necessary for your network.



901 Explorer Boulevard P.O. Box 140000 Huntsville, AL 35814-4000 Phone: (256) 963-8000

Copyright © 2022 Adtran, Inc. All Rights Reserved.

2 6ABSAP37141P-40A

vWLAN Patch Release Notes Table of Contents

Table of Contents

1.	Introduction	4
2.	Supported Platforms	4
3.	Wireless Regulatory Compliance	. 4
4.	Release-Specific Upgrade Instructions	5
_	Fixes	_
J .	rixes	J
6.	Errata	5
7.	Warranty and Contact Information	6

6ABSAP37141P-40A

Introduction vWLAN Patch Release Notes

1. Introduction

The 3.7.1 and 4.1 patch releases for Adtran's Bluesocket APs (BSAPs) are minor patch releases that address upgrade issues for factory default APs running on 7.0.0-23 when they are upgraded to the 3.7.1 or 4.1 vWLAN releases.

These patch releases are generally available code. Results obtained during internal testing have been evaluated and the code has been determined to be ready for general availability. Caveats discovered during testing but not addressed in this build are listed in *Errata on page 5*.

Configuration guides, white papers, data sheets, and other documentation can be found on Adtran's Support Community, https://supportcommunity.adtran.com. The contents of these release notes will focus on the platforms listed in <a href="https://supported.put/s

2. Supported Platforms

The following AP models are supported in the 3.7.1 and 4.1 patch releases:

Table 1. Supported Platforms

BSAP Platform
BSAP 1920/1925
BSAP 1930/1935
BSAP 1940
BSAP 2020
BSAP 2030/2035/2135
BSAP 3040/3045
BSAP 6040
BSAP 6120



NOTE

These patches only apply to factory default APs currently running on 7.0.0-23.

3. Wireless Regulatory Compliance

Based on the United States FCC and European DFS and ETSI regulations, Adtran validates the country in which the APs are being operated. This prevents the Adtran equipment from accidentally being used in an improper configuration.

When customers request AP licenses, they must specify the country in which the AP will be deployed and operated. Note that a single vWLAN instance can control and manage APs in different countries and regulatory domains, and that the channel and power settings are regulated by the county in which the individual AP is deployed and operating.

Before the license is installed, the AP is in the platform and not associated to any domain, so the AP's radios are disabled by default. When the licenses are uploaded, the country code is then applied to licensed BSAPs. Allowed channels and power levels are determined by the country and the platform; once the AP is placed into a domain, it scans the channels to discovery neighboring APs and select a valid channel.

4 6ABSAP37141-40A

4. Release-Specific Upgrade Instructions

The vWLAN patches for 3.7.1 and 4.1 apply only to APs running on firmware 7.0.0-23. Installing these patches allows the APs to upgrade to either the vWLAN 3.7.1 or vWLAN 4.1 releases by addressing upgrade issues between the SSH Ciphers on APs running 7.0.0-23 and vWLAN instances running 3.7.1 or 4.1.



NOTE

These patches are only applicable to factory default APs running firmware 7.0.0-23.

To successfully upgrade these APs, follow these steps:

1.Install the patch from vWLAN GUI (**Admin > Patch**), using either the 3.7.1 patch or the 4.1 patch (depending on the version of vWLAN to which you are upgrading).



NOTE

No **Platform** or **Domain** tasks are required for patch installation.

- 2. Once the patch is installed, the **sshd** version of the AP will be set to an older version (openssh-7.2) to allow the upgrade communication between the APs and vWLAN to function successfully.
- Begin the AP upgrade to either the vWLAN 3.7.1 or 4.1 releases. Refer to the Upgrading Bluesocket vWLAN Controllers and APs guide (available online at https://supportcommunity.adtran.com) for upgrade instructions.
- 4. When the upgrade is complete, Adtran recommends uninstalling the patch as it changes the SSH version. Once the patch is removed, the SSH version will return to the latest recommended version (openssh-8.4).

5. Fixes

This section highlights major bug fixes in the 3.7.1 and 4.1 patch releases.

■ BSAP-6333 Fixed an issue in which APs running on 7.0.0-23 failed to upgrade properly to either 3.7.1 or 4.1 because older ciphers were preventing the 7.0.0 firmware from communicating with vWLAN via SSH.

6. Errata

There are no errata associated with the 3.7.1 or 4.1 patch releases. Errata associated with the vWLAN 3.7.1 and 4.1 releases are specified in the vWLAN 3.7.1 Release Notes and vWLAN 4.1 Release Notes, available online at https://supportcommunity.adtran.com.

6ABSAP37141-40A 5

7. Warranty and Contact Information

Warranty information can be found online by visiting www.adtran.com/warranty-terms.

To contact Adtran, choose one of the following methods:

Department	Contact Information	
Customer Care	From within the U.S.: From outside the U.S.:	(888) 4ADTRAN ((888)-423-8726) +1 (256) 963-8716
Technical Support	Support Community: Product Support:	www.supportcommunity.adtran.com www.adtran.com/support
Training	Email: Adtran University:	training@adtran.com www.adtran.com/training
Sales	For pricing and availability:	1 (800) 827-0807

6 6ABSAP37141-40A