

# **Software Release Notes**

# **Release 2.4.2.8**

Relevant to SR Series Model(s):

SR10 SR100

SR100G SR300N

SR300NE

SmartRG Inc. Proprietary and Confidential. All rights reserved, Copyright© 2012.



# **Document History**

Version	Date	Author	Description
1.0	08/08/2012	M. Solomon	Document creation

#### **Notice of Document Integrity**

The contents of this document are current as of the date of publication. SmartRG Inc. reserves the right to change the contents without prior notice. In no event will SmartRG be liable for any damages or for commercial losses resulting from information contained in this document.



Page 2 of 6



# SW Revision Summary

SW	DSP/xDSL Line Driver	CFE	Wireless Driver	Release
Version		Version		Date
2.4.2.8	A2pB026.d22j	1.0.37-104.9	5.10.146.0cpe4.404	1/28/2013
2.4.2.7	A2pB026.d22j	1.0.37-104.9	5.10.146.0cpe4.404	8/6/2012
2.4.2.6	A2pB026.d22j	1.0.37-104.9	5.10.146.0cpe4.404	1/11/2012

#### **New Features**

New Features			
Ref#	Description Notes		
RB-243	DHCP Relay support added.		

## **Changes & Fixes**

Changes & Fixes			
Ref#	Description	Notes	
RB-36	Default PPP Authentication Retry Limit set to 65535		
<b>DD</b> 04	(Infinite)		
RB-91	RADIUS server IP field accepted invalid IP address. This		
	has been corrected.		
RB-168	LAN side firewall was not activating on startup.		
RB-176	Add PPP Authentication Retry to PPP connections		
	created by CnS.		
RB-234	STUN failed if connection to STUN Server was lost. STUN		
	would sometimes exit on startup. STUN retry wait period		
	was too long.		

#### **Known Issues**

Known Issues			
Ref#	Description Notes		
RB-23	Time blocking - browser redirect to block page may not work		
RB-28	Can't Disable DNS Proxy		



Page 3 of 6



# Compatibility/System Notes

Target download protection has been enabled which prevents downloads of incompatible image files.

IGMP Snooping Definitions:

<u>Standard Mode</u> - in standard mode, if multicast traffic is present on a LAN port but no membership report (join) was received, the traffic will flood to all ports. If a membership report was received, multicast traffic will be forwarded only to the LAN ports on which the IGMP membership reports arrived.

<u>Blocking Mode</u> - in blocking mode, multicast traffic will be blocked from all ports until such time a report is received.

If IGMP snooping is disabled the CPE floods multicast packets to all its ports. IGMP Snooping is disabled by default.

This software supports Physical Layer Retransmission (PhyR) which operates at layer 1 and uses a mechanism similar to TCP where retransmits occur if errors are detected. This results in high effective INP with minimal interleave delay. Sync rate increases from 2 to 4Mbps have been reported in addition to the line being more robust and resistant to noise/interference generated from treadmills, ceiling fans, etc. PhyR is disabled by default but can be enabled in the DSL menu.

MAC address considerations – the source MAC address contained in upstream data equals the base MAC address. The second WAN interface uses the base MAC address plus 4 (counted in hex). Additional WAN interfaces will increment by one. TR-069 will report the base MAC address in the CWMP protocol.

Wireless is enabled by default with SSID = SmartRGxxxx (x = last four characters of base MAC). Wireless security is Mixed WPA2/WPA-PSK, passphrase = OneCpeToRuleThemAll, Rekey interval = 0 and encryption = TKIP+AES.

Included PBCA Features:

- Control Panel
- Content Filtering
- Time Blocking
- Captive Portal
- Connect and Surf
- STUN and UDP Connection Request
- Advanced Connected Device Monitor
- Bandwidth Monitor
- WiFi Performance Monitor
- Dynamic Content Filtering



Page 4 of 6



## Prior SW Releases

2.4.2.7			
Ref#	Description		Notes
RB-14	Number of PPPoE retries on authentication error	r is now configurable	
RB-11	Resolved device not retrying PPPoE authentication after error		
RB-29	Resolved Primary DNS failure not triggering switch to Secondary		
RB-31	Resolved SSID not containing last 4 characters of MAC		
RB-9	Changed SSID: "ClearAccessxxxx" to "SmartRGxxxx" where xxxx is last 4 digits of MAC		
RB-9	Changed Default WEP Key from "ClearAccessWA "SmartRGWireless"	" to	

2.4.2.6		
Ref#	Description	Notes
SD-3328	Resolved incorrect LAN device status	

## SW Upgrade Procedure

Upgrade	e Software
Step	Description
1.0	Open a web browser, connect to 192.168.1.1/admin, and login with username <b>admin</b> and
	password <b>admin</b> (or appropriate IP address and login info)
2.0	Click Management→Update Software and select the Browse button
3.0	Locate and select the appropriate software image
4.0	Select the Update Software button. The software image will be uploaded to the device and the device will reboot automatically upon completion
Verify	
Step	Description
1.0	Hit the F5 Key to refresh your browser and reconnect to 192.168.1.1/admin to log back into the device
2.0	Click on Device Info
3.0	Verify the correct code is shown in the Software Version field
Restore	Defaults
Step	Description
1.0	Hit the F5 Key to refresh your browser and reconnect to 192.168.1.1/admin to log back into the modem
2.0	Click on the Management Link
2.1	Click on Settings
2.2	Click on Restore Default
Note:	Restoring device defaults can also be accomplished by momentarily pressing the reset button for at least seven seconds while powering on the device



Page 5 of 6



# Tech Support:

#### **CPE Issues:**

Submit a ticket using our Customer Portal at <a href="https://smartrg.atlassian.net">https://smartrg.atlassian.net</a>

#### RMAs:

Open a Customer Portal ticket of type 'RMA Request', with title and description beginning with "RMA", and attach a spreadsheet which includes Company Name, Model, MAC address, Issue and Firmware version tested.

#### Firmware:

Login to the Customer Portal to download firmware

#### **Additional Contact Info:**

Phone:+1 360 859 1780, Option 4 Hours: 5am – 5pm PST (UTC-0800) Email: support@smartrg.com



Page 6 of 6