



Q&A

When a PRI/BRI interface of a Cisco router dials an ISU it cannot make a MLPPP connection

Q:

When a PRI/BRI interface of a Cisco router dials an ISU it cannot make a MLPPP connection

A:

The Cisco router is dialing both numbers simultaneously. ADTRAN units do not support simultaneous answering of calls. The Cisco router must be set to dial the numbers one at a time. This can be done by adding the following command to the Cisco router configuration:

isdn fast-rollover-delay 1

The following is an example Cisco configuration:

```
interface BRI0
ip address 192.168.254.2 255.255.255.0
encapsulation ppp
ipx network 3002B
isdn spid1 97255591300101 5559130
isdn spid2 97255596910101 5559691
isdn fast-rollover-delay 1
dialer idle-timeout 2147483
dialer map ipx 3002B.00e0.b063.cb74 name kdmx broadcast 9725558716
dialer map ipx 3002B.00e0.b063.cb74 name kdmx broadcast 9725558717
dialer map ip 192.168.254.1 name kdmx broadcast 9725558716
dialer map ip 192.168.254.1 name kdmx broadcast 9725558717
dialer hold-queue 1
dialer load-threshold 1 outbound
dialer-group 1
no fair-queue
ppp authentication chap
ppp multilink
```
