

## / SOFTWARE RELEASE NOTES

---

Release 2.0.2.2

Relevant Model: SR804n

March 2018

## Table of Contents

- Introduction ..... 3
- Software MD5 ..... 3
- Default settings ..... 3
- Release 2.0.2.2 ..... 3
  - Fixes ..... 3
- Release 2.0.1.5 ..... 3
  - Features..... 3
  - Fixes ..... 3
  - TR181 Supported..... 3
  - MIB Supported..... 4
  - VSIF Supported ..... 5
  - Known issues ..... 5
- Release 2.0.1.4 ..... 5
  - Features..... 5
  - Fixes ..... 5
- Release 2.0.1.3 ..... 5
  - Features..... 5
  - Fixes ..... 6
- Release 2.0.1.2 ..... 6
  - Features..... 6
  - Fixes ..... 6
- Release 2.0.1.0 ..... 6
  - Features..... 6
  - Fixes ..... 6
- Release 1.0.0.5 ..... 7
  - Features..... 7
  - Fixes ..... 7
- Release 1.0.0.4 ..... 7
  - Features..... 7
  - Fixes ..... 7
- Release 1.0.0.3 ..... 7

- Features*.....7
- Fixes* .....7
- Release 1.0.0.2** .....7
  - Features*.....7
  - Fixes* .....8
- Release 1.0.0.1** .....8
  - Features*.....8
  - Fixes* .....8
- Compatibility/System Notes** .....8
- FW Upgrade Procedure** .....8
- Tech Support** .....8
  - CPE Issues*.....8
  - RMAs*.....8
  - Firmware*.....8
  - Additional Contact Info*.....8
- Document History**.....9

Notice of Document Integrity

The contents of this document are current as of the date of publication. SmartRG Inc. reserves the right to change the contents without prior notice. In no event will SmartRG be liable for any damages or for commercial losses resulting from information contained in this document.

## Introduction

This release note document provides detailed information about release 2.0.2.2 of the SR804n gateway.

## Software MD5

- SR804N\_v2.0.2.2\_s.bin; MD5: 8fee0efae5976a98e6f1e6633762bb5a

## Default settings

- SR804-25, Block Fragmented IP Packets Default OFF.
- SR804-26, Port Scan Detection Default OFF.
- SR804-26, IP Flood Detection Default OFF.
- SIP ALG set to OFF

**Note:** If upgrading from a previous release, factory restore may be required to obtain these new default settings.

## Release 2.0.2.2

### *Fixes*

- Fixed TR-069 abandonment issue.

## Release 2.0.1.5

### *Features*

- SR804-66 WAN access to port 8080 to mitigate potential security risk

### *Fixes*

- SR804-40 No method of setting DHCP reservation.
- SR804-81 "Received" and "Transmitted" traffic should not pass on Guest1-Guest6 after watching online TV on Guest0.
- SR804-86 When checking the bonded frequency via console, the CM crashes. (Occasional)
- SR804-89 When changing the PC address from automatic to manual while connected with the CM, the CM crashes. (Occasional)
- SR804-80 WLAN LED should blink quickly after watching online TV on WLAN CPE.
- SR804-63 USB page is no longer highlighted.

### *TR181 Supported*

- Device.X\_SMARTRG\_AcsControlPanelUrl
- Device.X\_SMARTRG\_AcsControlPanelRedirectEnable
- Device.X\_SMARTRG\_DownstreamChannels.{}.Channel
- Device.X\_SMARTRG\_DownstreamChannels.{}.LockStatus
- Device.X\_SMARTRG\_DownstreamChannels.{}.Modulation
- Device.X\_SMARTRG\_DownstreamChannels.{}.ChannelID

- Device.X\_SMARTRG\_DownstreamChannels.{}.Frequency
- Device.X\_SMARTRG\_DownstreamChannels.{}.Power
- Device.X\_SMARTRG\_DownstreamChannels.{}.SNR
- Device.X\_SMARTRG\_DownstreamChannels.{}.Correctables
- Device.X\_SMARTRG\_DownstreamChannels.{}.Uncorrectables
- Device.X\_SMARTRG\_UpstreamChannels.{}.Channel
- Device.X\_SMARTRG\_UpstreamChannels.{}.LockStatus
- Device.X\_SMARTRG\_UpstreamChannels.{}.USChannelType
- Device.X\_SMARTRG\_UpstreamChannels.{}.ChannelID
- Device.X\_SMARTRG\_UpstreamChannels.{}.SymbolRate
- Device.X\_SMARTRG\_UpstreamChannels.{}.Frequency
- Device.X\_SMARTRG\_UpstreamChannels.{}.Power
- Device.X\_SMARTRG\_CM\_IP\_Address
- Device.X\_SMARTRG\_CM\_Duration
- Device.X\_SMARTRG\_CM\_Expires
- Device.WiFi.SSID.10001.Enable
- Device.UserInterface.RemoteAccess.Enable
- Device.UserInterface.RemoteAccess.Port

## *MIB Supported*

- brcm-ssh-mgmt.mib
- brcm-telnet-mgmt.mib
- brcm-snmp-mgmt.mib
- brcm-smi.mib
- brcm-cabledata-smi.mib
- brcm-v2-mgmt.mib
- brcm-cabledata-mgmt.mib
- brcm-http-mgmt.mib
- brcm-ping-mgmt.mib
- brcm-ftp-mgmt.mib
- brcm-parentalcontrol-mgmt.mib
- brcm-cablehome-factory.mib
- brcm-cabledata-private.mib
- brcm-cabledata-engineering.mib
- brcm-cabledata-factory.mib
- brcm-cm-factory.mib
- brcm-v2-factory.mib
- brcm-cm-engineering.mib
- brcm-battery-engineering.mib
- brcm-battery-mgmt.mib
- brcm-80211-factory.mib
- brcm-wifi-factory.mib
- brcm-80211-mgmt.mib
- brcm-wifi-mgmt.mib
- brcm-usb-factory.mib
- brcm-bfc-mgmt.mib
- brcm-power-mgmt.mib
- brcm-thermal-mgmt.mib
- brcm-l2tpv3-mgmt.mib
- brcm-wifi-hotspot.mib
- brcm-rg-factory.mib

- brcm-l2ogre.mib
- brcm-rg-mgmt.mib
- brcm-cm-capability.mib
- brcm-cm-mgmt.mib
- brcm-iptv.mib
- brcm-cm-products.mib
- brcm-sw-dload.mib
- brcm-cm-mgmt-ext.mib
- brcm-host-sec.mib
- brcm-cablehome-mgmt.mib
- brcm-cm-ema-mgmt.mib
- brcm-ema-factory.mib

## *VSIF Supported*

N/A

## *Known issues*

- SR804-14 TR -069 - Cannot poll WiFi Strength
- SR804-15 TR - 069 - Cannot poll WiFi Standard.
- SR804-51 SR804n - WiFi Insight missing SmartRG branding (look and feel / colors)
- SR804-53 CPE reports a fault "Parameter Not Writeable"
- SR804-59 Implement Cisco PHP6.1.1\_BFC5.7.1mp2 For All SmartRG DOCSIS Gateways

## Release 2.0.1.4

### *Features*

None

### *Fixes*

- SR804-75 "Remove All" button removes System Default Port Forward for TR-069 (Port 30005);  
Was: Device stops responding to connection requests.
- SR804-76 System Start-up Time shouldn't be more than 55s.
- SR804-82 Default IPv4 TFTP Block size should be 1428 according to RFC2348.
- SR804-87 When configuring Parental Control as enabled, user can't open webpage with WAN IP on WAN side.
- SR804-88 When configuring Parental Control as enabled, the openacs platform can't connect with CM via 30005 port.
- SR804-90 The "Pass Through Mac Address" is lost after backing up a config file.
- WIFI disconnection issue.

## Release 2.0.1.3

### *Features*

- SR804-11 Subscriber WiFi SSIDs should be disabled when DUT is placed in Bridge Mode.
- SR804 -57 Statistics display in SR804n GUI should indicate the units of measure somewhere on this page

## Fixes

- SR804-21 Must pass FW upgrade/Downgrade test to/from prior GA releases.
- SR804 -48 CPE Requires reboot for CWMP Settings to take effect.
- SR804 -52 CPE reports an empty string in the Protocol Parameter
- SR804 -53 CPE reports a fault "Parameter Not Writeable"
- SR804 -55 SR804n Disable SIP ALG by default in Firmware (Was: SIP ALG causes reboot)
- SR804 -56 Firewall TR-181 parameter returns incorrect value
- SR804 -58 Status page's Statistics display can incorrectly display negative values for received/transmitted bytes on a given WAN and or LAN interface

## Release 2.0.1.2

### Features

- Add USB function
- Add support for selected TR181 objects via RDMS

### Fixes

- SR804-7 WiFi Passphrase cannot be imported
- SR804-16 RF Power MIB Reporting MUST meet DOCSIS Spec +/- 2dB.
- SR804-32 SR804N Wifi Channel Control - manual
- SR804-33 SR804N Wifi Channel Control - Auto
- SR804 -48 CPE Requires reboot for CWMP Settings to take effect.

## Release 2.0.1.0

### Features

1. WiFi hotspot(GRE Hotspot original from BFC5.7.1mp1).
2. Chip version upgrade from 5.7.1mp1beta2 to 5.7.1mp1.
3. SR804-5, TR-069 DOCSIS RF stats.
4. SR804-7, WiFi Passphrase cannot be imported.
5. SR804-8, GUI - Spectrum Analyzer - Add button Link to Spectrum Analyzer Page under Diagnostics Menu.
6. SR804-10, Broadcom WiFi-Insight Support.
7. SR804-15, TR - 069 - Cannot poll WiFi Standard.
8. SR804-40, SR804N No method of setting DHCP reservation.
9. SR804-30, TR-069 GUI Click-through.
10. Remove USB function.

### Fixes

- SR804-6, Cannot set the WiFi security mode
- SR804-37, SR804N - Parental Control Password in clear text
- SR804-38, SR804N ADMIN Password limited to 8 characters but allows more to be entered

## Release 1.0.0.5

### *Features*

- Chip version upgrade from 5.7.1mp1beta2 to 5.7.1mp.

### *Fixes*

None

## Release 1.0.0.4

### *Features*

None

### *Fixes*

- Firmware upgrade issue.
- Firmware downgrade issue.
- When loading a configuration using the CPE GUI, the TR069 setting were not updated.
- The 804 stops informing after an undetermined number of hours. In this case after just over 8 hours of informing to the ACS, the CWMP client goes to sleep until rebooted.
- Disable ICMP Rate-Limiting Feature.
- Firmware Co-sign issue.

## Release 1.0.0.3

### *Features*

- Implement SmartRG new version Web GUI
- Support super/user permission for telnet
- Update SDK to 5.5.10mp3
- Develop factory test command

### *Fixes*

- Open SSH, Telnet by default
- Fix NOR+NAND boot up issue
- Merge H/W downstream/Upstream power offset
- Merge Wi-Fi SROM into code
- Address DLNA not functioning in previous releases
- Fix memory leak issue

## Release 1.0.0.2

### *Features*

- Support TR69



## *Fixes*

- Fix some bugs on SmartRG old version Web GUI

## Release 1.0.0.1

## *Features*

- Implement SmartRG old version WEB UI.

## *Fixes*

- Firmware upgrades issue.

## Compatibility/System Notes

None

## FW Upgrade Procedure

Contact your provider for assistance.

## Tech Support

### *CPE Issues*

Submit a ticket using our Customer Portal at <https://smartrg.atlassian.net>

### *RMA's*

Open a Customer Portal ticket with description "RMA" and attach a spreadsheet which includes Model, MAC address, Issue, and Firmware version.

### *Firmware*

Login to the Customer Portal to download firmware.

### *Additional Contact Info*

Phone: +1 360 859 1780, Option 4 Hours: 5am -5pm PST (UTC-0800) Email: [support@smartrg.com](mailto:support@smartrg.com).

## Document History

VERSION	DATE	AUTHOR	DESCRIPTION
1.0	12/30/14	Adam Fox	Document Creation
1.1	5/25/16	David La Cagnina	Layout Modified
1.2	6/30/16	Kurt Diekemper	Updated minimal info & review
1.3	7/10/16	Kurt Diekemper; Rafael Valencia	Updated based on additional review.
1.4	3/29/18	Kurt Diekemper	Updated info for 2.0.2.2