

ADTRAN vWLAN 2.5.1/2.6.1 Critical Security Patch for BSAP Impersonation Vulnerability

Releases Affected By Vulnerability: All BlueSocket vWLAN releases

Patch Names:

- security-2.6.1.06-1.patch (Requires vWLAN version 2.6.1.06)
- security-2.5.1.07-1.patch (Requires vWLAN version 2.5.1.07)

Document Date: October 28, 2015

These Release Notes list fixes, known issues, and other important information about this patch developed for vWLAN.

Contents

Important Notices	2
Previous Patches	2
Patches and High Availability.....	2
Uninstalling Previous Patches.....	2
Installing Patches	2
Fixes.....	3
security-2.6.1.06-1.patch and security-2.5.1.07-1.patch.....	3
Errata.....	3

Important Notices

Previous Patches

These patches address a specific issue for multiple vWLAN versions and do not include fixes from previous patches.

Patches and High Availability

In a high availability network configuration, each vWLAN platform must have patches installed individually (patches are not replicated between the primary and secondary vWLAN instances).

Uninstalling Previous Patches

Previous patches do not need to be removed prior to installing this patch. Note that a reboot is necessary following the removal of patches.

1. Navigate to the **Administration** tab and select **Patch**
2. Select the patch to delete and click **Delete**.
3. Once the patches have been removed, reboot vWLAN.

Installing Patches

Note that a reboot is not necessary following the installation of this patch.

1. Navigate to the **Administration** tab and select **Patch**
2. Select the patch to install using the **Browse** button.
3. Select **Install**.
4. Any patches that you have installed will be visible in the **Patch list**. A **Platform Task** should display stating that a reboot is required.

Fixes

security-2.6.1.06-1.patch and security-2.5.1.07-1.patch

Resolves an issue where a remote attacker could potentially impersonate a Bluesocket access point, upload arbitrary script to the Bluesocket vWLAN, and remotely execute that arbitrary script.

Errata

Known issues are outlined in the and [vWLAN Version 2.6.1.06 Release Notes](#) and [vWLAN Version 2.5.1.07 Release Notes](#) in the [ADTRAN Support Community](#).