



Article ID: 1413

Q&A

What does the status message NO WINK FROM CO mean on a V.34 card in a TSU/DSU ESP?

Q:

What does the status message NO WINK FROM CO mean on a V.34 card in a TSU/DSU ESP?

A: There are three possibilities:

- a. There is an open loop condition on the DBU card. Change the connector from an RJ-11 to an RJ-45.
 - b. The analog line has noise on it and is not properly communicating with the PBX.
 - c. It is the equivalent of a fast busy signal from the PBX.
-