

501 SE Columbia Shores Boulevard, Suite 500 Vancouver, Washington, 98661 USA +360 859 1780 / smartrg.com

/ SOFTWARE RELEASE NOTES

SMARTOS 10.5.4.1

August 2018



SmartOS SW Revision Summary

Firmware	Description	Date
10.6.3.1	Various fixes and enhancements; see lists for details.	
10.5.4.1	Various fixes and enhancements; see lists for details.	8/16/18
10.5.2.1	Various fixes and enhancements; see lists for details. 6/29/18	
10.4.7.1	Various fixes and enhancements; see list for details. 3/5/18	
10.3.8.1	WebUI redesign; enhanced features. 6/30/17	
10.2.1.1	Initial GA Release for SR400ac. 6/30/1	



SR400ac/SR90xac Product Description

- · Gigabit Residential Gateway
- 1x Gigabit Ethernet WAN
- 1x SFP WAN (SR900ac only)
- 4x Gigabit Ethernet LAN
- Dual-band concurrent WiFi (5GHz, 2.4GHz)
 - o SR400ac: 3x3 11n + 3x3 11ac
 - o SR900ac: 4x4 11n + 4x4 11ac
- 1x USB2
- 1x USB3

SR400ac/SR90xac Features

- WAN Configuration Modes: DHCPv4, Static, PPPoE
- WAN VLAN Tagging Modes: Untagged, Tagged, Double Tagged (QinQ)
- TR-069 Management (TR-181 data model) with STUN
- HTTP Interface
- CLI Interface via SSH
- Smart Modem Manager (hairpin redirect to upstream WAN device)
- NAT/Firewall
- IGMP Snooping
- IGMP Proxy (v2/v3)
- IPv6
- · NetData statistical graphs

Revision 10.5.4.1

New Features/Enhancements in 10.5.4.1

• Not applicable; this revision is a hot-fix for 10.5.2.1.

Fixes in 10.5.4.1

	Description	
OWRT-2477	Addressed problem affecting Upgrade via TR-069	

Release Image for 10.5.4.1

SR400ac:

Filename: SmartOS-SR400ac-v10.5.4.1.img

md5sum: 8a1f2fe5020909f9fef6a9c5864e1998

SR900ac:

Filename: SmartOS-SR900ac-v10.5.4.1.img

md5sum: b7e8ac1361a5f21a1be58712caab7b3c



Revision 10.5.2.1

New Features/Enhancements in 10.5.2.1

- Intellifi Mesh WiFi
 - Zero-touch provisioning of satellites by hub

 - Config synchronization from hub to satellites
 Auto-generate network topology map
 Aggregation of network/wireless stats from satellites to hub
 Firmware management of satellites by hub
 Auto-discover topology of PL60/MC60
 Automatic updates (upon request)
- SR900ac POTS v1.0
 - o Metaswitch SIP interoperability
 - o Advanced telephony feature configuration
 - Call trace
 - TR-104
 - Interop may be needed
- VDSL2/ADSL2+ (Alpha-stage, software available upon request)

Fixes in 10.5.2.1

Ref ID	Description	
OWRT-2773	Prevent websocket timeout when webUI user is idle	
OWRT-2827	Report current network status of LAN devices	
OWRT-1483	WebUI glitches in Access Schedules page	
OWRT-2419	WebUI crash following series of quick clicks	
OWRT-2691	More accurate webUI progress bars for Reboot, Restore Factory, and Upgrade operations	
OWRT-2614	Configuration of DHCP Static Associations in webUI	
OWRT-2350	Incomplete 2.4GHz WiFi scan at boot	
OWRT-2534	Unable to save Backup Config	
OWRT-2030	Stun configuration migration when upgrading from SmartOS 10.3	
OWRT-2009	Always disable stund when TR-069 is disabled	
OWRT-2384	SR400ac multicast delivery issues with mix of wired and WiFi STBs	
OWRT-2278	Correct lower-case MAC in manufacturing data on old hardware	
OWRT-2321	Basic Setup page alignment issues	
OWRT-2401	Correctly handle 32-character SSID	
OWRT-1973	Port forward config not saved when changing port range to port	
OWRT-2405	Incorrect uses count on dashboard due to inclusion of inactive LAN hosts	
OWRT-2795	Fix edit button on Hosts page	
OWRT-1625	ACS erroneously reports duplicate Port Mapping objects	



Ref ID	Description	
OWRT-2842	Clear Log button not functional in webUI	
OWRT-2264	Javascript error on Network->LAN->Devices page	
OWRT-2438	Display glitches in WiFi Performance pages	
OWRT-2477	Inadequate firmware Image validation for TR-069 upgrade	
OWRT-2247	Inadequate firmware image validation for webUI	
OWRT-2234	APPLY banner does not appear following enable of Network Protection	
OWRT-1794	Duplicate error message following attempted configuration of invalid LAN address	
OWRT-2446	Fixed race condition in webUI backend when committing large set of changes	

Changes in 10.5.2.1

- WebUI updated look and feel
- WiFi SSID configuration moved from Radio interface page to Wireless Networks page
- Added HTTP proxy
- Added 5G Guest WiFi for SR900ac
- Added display of optic stats on SR900ac

Known Issues/Limitations in 10.5.2.1

DSL does not yet support ATM encapsulation (DSL only turned on in custom CDT)

Release Image for 10.5.2.1

SR400ac:

Filename: SmartOS-SR400ac-v10.5.2.1.img

md5sum: f29e68d90f4341810b4c8d5f7c0433d5

SR900ac:

Filename: SmartOS-SR900ac-v10.5.2.1.img

md5sum: cf5eb350880b78294c938eb4888cc74b

Revision 10.4

New Features/Enhancements in 10.4

- - Support for Access Point mode 0
 - Monitor QBSS Load of adjacent Access Points
 - o Advanced Airtime/Performance Monitoring Advanced Airtime/Performance Monito
 Advanced Airtime Client Performance
 Support for IJSR LTF M/AN

 - LTE Failover with per-host filtering
- Networking
 - o IPv6: Dual Stack
 - Expanded Guest LAN Config options



- o DHCP Option 60 Vendor Class Identifier
- WebUI
 - Challenge Authentication
 - o Internationalization: Support for Spanish, French, and German, switchable on the fly
 - Updated Dashboard and improved menu layout
 - o Add/Delete webUI pages dynamically based on device state
 - o Redesigned Firewall pages to protect users from common mistakes
 - o Password recovery help to login page upon login fail
 - Optional auto-logout on inactivity
 - o Notification if booted into MFG mode
 - Improved responsiveness for mobile clients
 - o Support wired Ethernet hosts in dashboard and top talkers
- Management
 - New CWMP Client and rewritten TR181 DM
 - o Expanded data model
 - o Axiros and Incognito Interop
 - Add router aliases http://setup and http://router
- Manufacturing
 - o Enter MFG mode through button hold sequence
- Network Security
 - Whole Home Ad and Malware Blocking

Fixes in 10.4

Ref ID	Description	
OWRT-601	Allowed cancellation of firmware image upload in webUI.	
OWRT-1201	Improved validation of user input on SNMP config page.	
OWRT-1565	Added Lost Password message/help on webUI login page after authentication failure.	
OWRT-1603	Added display of STUN server configuration in webUI.	
OWRT-1663	Added Challenge Response Authentication for webUI clients.	
OWRT-1710	Prevented persistence of MAC in config when restored to another device.	
OWRT-1724	Disallowed addition of duplicate firewall rules.	
OWRT-1769	Prevented duplicate confirmation dialogs on webUI Router Access page.	
OWRT-1817	Addressed connectivity issue following addition of firewall rules.	
OWRT-1913	Addressed alignment of Upgrade button on webUI firmware updates page.	
OWRT-1929	Improved image validation message and functionality on upgrade page.	
OWRT-1935	Corrected Retry rate calculations to prevent greater than 100% results within GUI statistics.	
OWRT-1939	Added max and min limits to VLAN and P-bit fields in Internet WAN and Video WAN pages.	
OWRT-1942	Addressed issue on tagged WANs where WAN interface name was not updated consistently across UI.	
OWRT-1947	Addressed issues with the Device and Station counters reporting inconsistently.	
OWRT-1953	Updated to latest dnsmasq to patch vulnerability.	
OWRT-1956	Addressed issue regarding SSID reporting that occurs when changing radio bands.	



Ref ID	Description	
OWRT-1982	Added Forgot My Password link to Login page.	
OWRT-1991	Expanded IPv6 addresses in tables throughout UI.	
OWRT-2000	Set auto-logout to optional.	
OWRT-2023	Added guest wireless DHCP server settings to UI.	
OWRT-2050	Improved top talker functionality on Dashboard.	
OWRT-2111	Reduced tiling in video when there is contention in the switch.	
OWRT-2132	Reported friendly device name to SHA.	
OWRT-2134	Allowed AP mode to be set in Wi-Fi.	
OWRT-2153	Prevented Wi-Fi config corruption on power loss during boot.	
OWRT-2161	Allowed setting AP mode in web UI QuickStart (to match feature in Wi-Fi QuickStart).	
OWRT-2174	Enhanced LAN-LAN throughput performance by allowing user to disable Port Isolation.	
OWRT-2194	Set Guest Wireless Enabled toggle to Off when the respective wireless radio is disabled.	
OWRT-2211	Addressed issue with SHA not responding to the SR400ac with proper data.	
OWRT-2225	Addressed metacharacter handling issue within the router which caused admin and support passwords to be defaulted.	
OWRT-2228	Disallowed config of Video port when Port Isolation is disabled.	
OWRT-2230	Addressed issue with errors when stopping or restarting processes.	
OWRT-2260	Advertise supported WiFi security modes in TR181.	
OWRT-2279	Addressed issue with migration from older FW which impacted ACS interop.	
OWRT-2296	Changed SHA client to report device ID as base MAC, rather than serial number.	

Known Issues in 10.4

None.

Release Image for 10.4

Filename: SmartOS-SR400ac-v10.4.7.1.img

md5sum: 2d15e681103dfd07f0bd5af4fbd881d8



Revision 10.3

New Features/Enhancements in 10.3

- WiFi
 - Guest Network
 - Access Point Scan
 - o HT40 with OBSS
 - Auto-channel selection
 - Connected Client List
- Parental Controls
 - o Content Filtering via OpenDNS Family Shield
 - o Time Blocking (per-device and per-group via Access Schedule)
 - o Manual pause of device and device-group
- Media
 - Network File Sharing
 - o DLNA
 - Cloud Storage Integration (box.com)
- Management
 - o Provision ACS URL via DHCP Option 43
 - SmartRG Home Analytics (SHA)
 - Display STUN client config
 - Dynamic DNS
 - o DHCP Clients
 - o MAC Cloning
- Performance
 - Real-time performance graphs
 - Dashboard
 - QoS options for gaming and Netflix
 - Per-Port Egress Rate Limiting
- IPTV
 - Support for IPTV modes: untagged/tagged/dqtagged WAN + untagged/tagged Video
 - Video Analyzer
 - o IGMP Group Memberships
- Other
 - Static Hosts
 - UK WiFi Support
 - Custom WebUI via Custom Defaults and Themes (CDT)

Changes in 10.3

- The LAN MAC is Base-MAC + 1
 Ex: If Base-MAC = 3C:90:66:00:12:80, then LAN MAC is 3C:90:66:00:12:81.
- The default password for the "support" user is the last 3 octets of the base MAC, with separating colons, all
 caps.

Ex: If Base-MAC = 3C:90:66:00:1A:80, then "support" password = 00:1A:80.



Fixes in 10.3

Ref ID	Description	
OWRT-541	SR400ac incorrectly reporting up time	
OWRT-567	Set default hostname to SR400+< <i>last-4-digits-of-base-mac</i> >	
OWRT-587	Addressed issue where remote http authentication was inoperative after "support" account password updated with special ascii characters (via TR-069)	

Known Issues/Limitations in 10.3

• IPv6 is disabled in this release

Release Image for 10.3

Filename: SmartOS-sr400ac-v10.3.8.1.imgmd5sum: 9465f83c9b04ac66df794b3cf11a5334



Upgrade Notes

Upgrading from 10.2.X releases:

• In the Web UI, navigate to System -> Backup/Flash Firmware to perform upgrade.

Upgrading from 10.3.X pre-releases:

- In the Web UI, navigate to ADMIN -> Update to perform upgrade.
- After uploading file, select Reset All Configuration and click Upgrade.

Verify

- 1. After the device reboots (~5 minutes), press the F5 key to refresh your browser and reconnect to http://192.168.1.1/.
- 2. Log back into the device.
- 3. Verify the version information in the **Software Version** field.



Technical Support

CPE Issues

Submit a ticket using our Customer Portal at https://smartrg.atlassian.net.

RMAs

Open a Customer Portal ticket with description "RMA" and attach a spreadsheet which includes Model, MAC address, Issue, and Firmware version.

Firmware

Login to the Customer Portal to download firmware.

Additional Contact Info

Phone: +1 360 859 1780, Option 4 Hours: 5am -5pm PST (UTC-0800) Email: support@smartrg.com



Document History

VERSION	DATE	AUTHOR	DESCRIPTION
1.0	12/30/14	Adam Fox	Document Creation
1.1	6/30/16	Adam Fox	Update for SmartOS 10.2.1.1
1.2	6/30/17	Adam Fox	Update for SmartOS 10.3.8.1
1.3	3/5/18	Adam Fox Kurt Diekemper	Update for SmartOS 10.4.
1.4	6/29/18	Adam Fox Kurt Diekemper	Update for SmartOS 10.5.
1.5	8/16/18	Adam Fox Kurt Diekemper	Update for SmartOS 10.5.4.1
1.6	11/29/18	Adam Fox Kurt Diekemper	Update for SmartOS 10.6.x