ADTRAN

Q&A

What is the Link Failed alarm on a TSU?

Q:

What is the Link Failed alarm on a TSU?

A:

Link Failed means that the TSU product is unable to communicate with the module in the slot with the alarm. Remove the card and reseat it. Also, turn the TSU off and back on to allow it to re-establish communication with the card.