Corporate Office

Adtran, Inc. 901 Explorer Boulevard Huntsville, AL 35806

U.S. Mail

P.O. Box 140000 Huntsville, AL 35814-4000

General Information

800 9ADTRAN info@adtran.com www.adtran.com

Pre-Sales
Technical Support
800 615-1176
application.engineer@adtran.com
www.adtran.com/support

Post-Sales
Technical Support
888 423-8726
support@adtran.com
www.adtran.com/support

ACES Help Desk 888 874-ACES aces@adtran.com www.adtran.com/support

Initial Release NotesIP 700 Series Phones

Firmware Version 1.3.3 November 30, 2007

Overview

The new IP 700 series IP Phones from ADTRAN are available to our IPT Dealers to be installed with the NetVanta 7100. Since this is the first release of these phones, we felt it was necessary to ensure our IPT Dealers know the major functional differences between our new phones and our existing co-brand ADTRAN/Polycom phones. We have worked hard to ensure our new phones are intuitive and functional. There are however a couple of areas listed below that represent items/functions that do not act as expected when compared to our co-brand ADTRAN/Polycom phones. Some of these items are a high priority and will be resolved in a future release of firmware. See Appendix A for Related Documentation.

• **GUI Support in the 7100**: NetVanta 7100 firmware version A1.01.00 will add GUI support for building IP 700 phone configurations. Until that version is released, the phone configurations must be built manually.

Overview 2

Notices for Version 1.3.3

The following is a list of notices for the initial firmware release of the IP 700 Series Phones (Version 1.3.3)

Mute Operation

Detail

While mute is enabled on the phone, switching between speakerphone, headset, or handset will cause the mute to be disabled on the phone.

Solution

Re-enable mute after switching between speakerphone, headset and handset.

Shared Line Account Transfer

Detail

The transfer key does not automatically select a second line on a SLA call.
 Solution

 Press the Transfer key, and then select a second line. When dialtone is heard, dial the number, then press the Transfer key to transfer the call.

Answer Softkey Operation

Detail

 Pressing this key on the first incoming call will answer the call. Pressing this key on the second incoming call (while still on the original call) will only ignore the call waiting notification.

Solution

 Press the line key to answer the second call or place the first call on Hold and then press Answer.

Shared Line Account Key Label

Detail

When a SLA line is active, the line label disappears.

Solution

This will be resolved in a future release of firmware for the IP 700 Series Phones.

Park Zone and Status Group/BLF

Detail

- One touch park/retrieve via a BLF key is not currently supported in the IP 700 Series Phones. Reference
- See user documentation for information on Park/Retrieve procedures on the IP 700 Series Phones.

Appendix A – Related Documents

For configuration guides, installation guides, white papers and more, visit ADTRAN's knowledge base at http://kb.adtran.com.

IP 700 Series Admin Guide -

http://kb.adtran.com/article.asp?article=2254&p=2

IP 700 Series Quick Reference Guide -

http://kb.adtran.com/article.asp?article=2257&p=2

IP 706 Quick Start Guide -

http://kb.adtran.com/article.asp?article=2255&p=2

IP 712 Quick Start Guide -

http://kb.adtran.com/article.asp?article=2256&p=2

IP 700 Series User Manual -

http://kb.adtran.com/article.asp?article=2253&p=2

Configuring the NetVanta 7100 for the IP 700 Series Phones -

http://kb.adtran.com/article.asp?article=2258&p=2