

AOS 13.15.00 Release Notes

Release Notes Release Date: January 30, 2012 Notes Revision: February 8, 2012

Resolved Issues

These are issues that have been resolved since the previous AOS release (13.14.00)

Under certain conditions, TCP sessions are not closed down properly due to the firewall dropping the TCP RST segment.

Attempting to configure ppp authentication through the web interface could cause a 503 server error.

In rare cases, a NetVanta 1224 could reboot due to a spanning-tree congestion issue.

Random text from an attached modem can eventually overload the buffer in the console port and cause a reboot.

Fixed a VPN issue with aggressive mode when connnecting to Avaya VPN phones

Repeated attempts of connecting to a unit with SSH could cause a reboot.

Input and Output interface counters were not always displaying the correct values.

Using SNMP over a long period of time could eventually cause a unit to run out of memory and reboot