

/SOFTWARE RELEASE NOTES

v 1.0.0.3 Gateway Model: SR804n



FIRMWARE RELEASE NOTES - SR804N

Firmware: v1.0.0.3

Hardware: CMM1.2U23W-4 SDK version: 5.5.10mp3

Issues Resolved

None

- 1. Merge downstream/upstream power offset.
- 2. Changed some default settings.
- 3. Fixed various Web GUI issues.
- 4. Fixed stability issues that followed firmware upgrade failure.
- 5. Modified User and Admin access permissions and ensured the appropriate information is displayed.
- 6. Updated Web GUI to new logo and format.
- 7. Changed default settings for IPSec ,PPTP Passthrough, Port Scan Detection and IP Flood detection, WiFi, and TR-069.

Enhancements:	
None	
Known Issues:	