

501 SE Columbia Shores Boulevard, Suite 500 Vancouver, Washington, 98661 USA +360 859 1780 / smartrg.com

/ SOFTWARE RELEASE NOTES

SmartOS

Version 1.2 June 2017



SmartOS SW Revision Summary

Firmware	Description	Date
10.3.8.1	Interface redesign; enhanced features	6/30/17
10.2.1.1	Initial GA Release for SR400ac	6/30/16



SR400ac Product description

- Gigabit Residential Gateway
- 1x Gigabit Ethernet WAN
- 4x Gigabit Ethernet LAN
- Dual-band concurrent WiFi (5GHz, 2.4GHz)
- 1x USB2
- 1x USB3

SR400ac Features

- WAN Configuration Modes: DHCPv4, Static, PPPoE
- WAN VLAN Tagging Modes: Untagged, Tagged, Double Tagged (QinQ)
- TR-069 Management (TR-181 data model) with STUN
- HTTP Interface
- CLI Interface via SSH
- Smart Modem Manager (hairpin redirect to upstream WAN device)
- NAT/Firewall
- IGMP Snooping
- IGMP Proxy (v2/v3)

Revision 10.3

New Features/Enhancements

- WiFi
 - Guest Network
 - o Access Point Scan
 - o HT40 with OBSS
 - o Auto-channel selection
 - Connected Client List
- Parental Controls
 - Content Filtering via OpenDNS Family Shield
 - o Time Blocking (per-device and per-group via Access Schedule)
 - Manual pause of device and device-group
- Media
 - Network File Sharing
 - o DLNA
 - Cloud Storage Integration (box.com)
- Management
 - o Provision ACS URL via DHCP Option 43
 - SmartRG Home Analytics (SHA)
 - Display STUN client config
 - Dynamic DNS
 - o DHCP Clients
 - o MAC Cloning



- Performance
 - o Real-time performance graphs
 - o Dashboard
 - QoS options for gaming and Netflix
 - o Per-Port Egress Rate Limiting
- IPTV
 - Support for IPTV modes: untagged/tagged/dqtagged WAN + untagged/tagged Video
 - Video Analyzer
 - o IGMP Group Memberships
- Other
 - Static Hosts
 - o UK WiFi Support
 - o Custom WebUI via Custom Defaults and Themes (CDT)

Changes in 10.3

- The LAN MAC is Base-MAC + 1
 Ex: If Base-MAC = 3C:90:66:00:12:80, then LAN MAC is 3C:90:66:00:12:81.
- The default password for the "support" user is the last 3 octets of the base MAC, with separating colons, all caps.

Ex: If Base-MAC = 3C:90:66:00:1A:80, then "support" password = 00:1A:80.

Fixes

REF ID	Description	
OWRT-541	SR400ac incorrectly reporting up time	
OWRT-567	Set default hostname to SR400+	
OWRT-587	SR400ac – remote http authentication inoperative after "support" account password updated with special ascii characters (via TR-069)	

Known Issues/Limitations

• IPv6 is disabled in this release



Release Image

Filename: SmartOS-sr400ac-v10.3.8.1.imgmd5sum: 9465f83c9b04ac66df794b3cf11a5334

Upgrade Notes

Upgrading from 10.2.X releases:

• In the Web UI, navigate to System -> Backup/Flash Firmware to perform upgrade.

Upgrading from 10.3.X pre-releases:

- In the Web UI, navigate to ADMIN -> Update to perform upgrade.
- After uploading file, select Reset All Configuration and click Upgrade.

Verify

- 1. After the device reboots (~5 minutes), press the F5 key to refresh your browser and reconnect to http://192.168.1.1/.
- 2. Log back into the device.
- 3. Verify the version information in the **Software Version** field.



Technical Support

CPE Issues

Submit a ticket using our Customer Portal at https://smartrg.atlassian.net.

RMAs

Open a Customer Portal ticket with description "RMA" and attach a spreadsheet which includes Model, MAC address, Issue, and Firmware version.

Firmware

Login to the Customer Portal to download firmware.

Additional Contact Info

Phone: +1 360 859 1780, Option 4
Hours: 5am -5pm PST (UTC-0800)
Email: support@smartrg.com



Document History

Version	Date	Author	Description
1.0	12/30/14	Adam Fox	Document Creation
1.1	6/30/16	Adam Fox	Update for SmartOS 10.2.1.1
1.2	6/30/17	Adam Fox	Update for SmartOS 10.3.8.1